



SRMC-STI-2022-00154
Revision 0

Annual Radioactive Waste Tank Inspection Program – 2021

June 2022

Approvals

Authors:

Ruel S. Waltz Jr. Digitally signed by Ruel S. Waltz Jr.
Date: 2022.06.14 13:09:36 -04'00'

Ruel S. Waltz, Jr.
Structural Authority and Inspection Engineering

Date

Technical Review:

09639 Digitally signed by O9639
Date: 2022.06.14 13:18:30
-04'00'

Alan S. Plummer
Structural Authority and Inspection Engineering

Date

Management Review:

09639 Digitally signed by O9639
Date: 2022.06.14 13:19:05
-04'00'

Alan S. Plummer
Structural Authority and Inspection Engineering

Date

Executive Summary

The Department of Energy (DOE) requires that Savannah River Mission Completion LLC (SRMC), the Liquid Waste contractor, maintain a robust and timely Structural Integrity Program for waste tanks that are leak-tight and for waste tanks that have leaked or are suspect. These requirements are promulgated in DOE Manual 435.1-1, Section II.Q.(2). A key aspect of SRMC's implementation of these requirements is its annual tank inspection program.

In 2021, the SRMC In-Service Inspection Program used two visual imagery techniques to ascertain the integrity of the Savannah River Site (SRS) waste tanks: high resolution digital photography and closed-circuit television. The primary inspection method made use of direct photograph techniques, e.g., making a series of photographs providing detailed views of the primary and secondary tank and wide-angle photography for obtaining overviews of large areas. Closed-circuit television was then typically used to further investigate conditions found during the initial inspection. During 2021, a total of 7,222 photographs were taken and 72 video inspections were performed as part of this inspection program.

Of the 51 waste tank systems at SRS that were designed, constructed, and placed into active service storing radioactive liquid waste, 43 remain in active service. Eight tanks have been cleaned, stabilized by filling with engineered grout, and removed from service (also known as operationally closed) – Tanks 5, 6, and 12 (Type I tanks); Tank 16 (Type II tank); and Tanks 17, 18, 19, and 20 (Type IV tanks). For the 43 waste tanks, inspections were successfully conducted in 2021 through all accessible annulus risers and inspection ports for nine Type I tanks, three Type II tanks, and 27 Type III/IIIA tanks; at least one inspection was made in the interior of four Type IV tanks (i.e., the tanks without annular spaces) above the liquid level in the tank.

Rainwater continues periodically to be observed migrating into the annuli of some tanks. Evidence of this infiltration was primarily noted by observation of surface stains, and occasionally by calciferous deposits, changed configuration of salt deposits in the associated annulus, and mild surface corrosion. The conditions of the 43 tanks remained essentially unchanged from the conditions reported in 2020. One key exception was the identification of two new cracks in the Tank 10 primary tank wall. These newly identified cracks are located at 110 and 129 inches above the tank bottom. The identified cracks in Tank 10 do not constitute an impact on the structural integrity of the tank, as evaluated and documented in the referenced reports, SRR-LWE-2021-00166 and SRR-LWE-2022-00001. **The 2021 inspection program confirmed the structural integrity and waste confinement capability of all 43 waste tanks.**

In addition to the visual tank inspections, the SRMC In-Service Inspection Program and the Structural Integrity Program requires periodic visual walkdowns to inspect specific ancillary equipment. These walkdowns are in addition to the camera/video inspections documented in Appendix A. During 2021, inspections were conducted on the following equipment:

- T-DS-G-00026, HDB-8 Process Vessel Ventilation System
- T-DS-G-00027, HDB-8 Diesel Generator
- T-DS-G-00056, Tank 48 Oxygen Analyzers
- T-DS-G-00057, Normal Nitrogen System
- T-DS-G-00065, 242-25H Evaporator Primary Ventilation System

For all the ancillary equipment inspected in 2021, no material degradation was noted that would prevent the equipment from performing its credited function.

A third facet of the SRMC Structural Integrity Program is the performance of ultrasonic nondestructive examinations (UT) on the waste tanks on a routine schedule. In 2021, ultrasonic testing inspections were performed on Tanks 47, 48 and 51, per this schedule. Inspections performed in Tanks 25 and 41 were per the Corrosion Control Program. **These examinations showed no reportable thinning, pitting, stress corrosion cracking, or evidence of service induced thinning of the primary tank wall, or the secondary liner wall and floor.**

Consistent with the provisions set forth in the Industrial Wastewater Treatment Facility Construction Permit for F-Area Tank Farm (FTF) and H-Area Tank Farms (HTF) liquid radioactive waste storage tanks, construction permit number 17,424-IW, this annual structural integrity report is provided to the South Carolina Department of Health and Environmental Control (SCDHEC) and the U.S. Environmental Protection Agency (EPA).

Table of Contents

Approvals	2
Executive Summary	3
List of Figures	6
List of Tables	6
Acronyms	7
1 Introduction	8
2 Requirements	8
3 Waste Tank Descriptions	9
3.1 Type I Tanks.....	10
3.2 Type II Tanks.....	13
3.3 Type IV Tanks.....	16
3.4 Type III/IIIA Tanks.....	20
4 Inspection Program Description	23
4.1 Background.....	23
4.2 Inspection Methods	25
4.3 Visual Imagery.....	25
5 Calendar Year 2021 Inspection Program Results	26
5.1 Overview	26
5.2 Tank Inspection Summary Sheets	27
6 Conclusion	72
7 References	72
Appendix A – Summary of 2021 Inspection	74
Acronyms	74
Distribution	128

List of Figures

Figure 3.1-1: Construction of the Type I Tanks in FTF	11
Figure 3.1-2: Typical Type I Tank Cross-Section.....	11
Figure 3.1-3: Typical Type I Tank Floor Configuration	12
Figure 3.1-4: Typical Type I Tank Access Area	13
Figure 3.2-1: Construction of the Type II Tanks in HTF.....	14
Figure 3.2-2: Typical Type II Tank Cross-Section.....	14
Figure 3.2-3: Typical Type II Tank Access Area	16
Figure 3.3-1: Construction of Type IV Tanks	17
Figure 3.3-2: Steel Bands and Turnbuckles on the Type IV Tank Walls.....	18
Figure 3.3-3: Typical Type IV Tank Cross-Section	18
Figure 3.3-4: Typical Type IV Tank Access Locations	19
Figure 3.4-1: Typical Construction of Type III/IIIA Tanks	20
Figure 3.4-2: Typical Type III Tank Cross-Section.....	21
Figure 3.4-3: Typical Type IIIA Tank Cross-Section	22
Figure 3.4-4: Typical Type III/IIIA Tank Access Locations.....	23

List of Tables

Table 3-1: Summary of SRS Waste Tank Design Types	10
---	----

Acronyms

ASME	American Society of Mechanical Engineers
CCP	Corrosion Control Program
DOE	Department of Energy
DSA	Documented Safety Analysis
EPA	Environmental Protection Agency
FFA	Federal Facility Agreement
FTF	F-Area Tank Farm
HTF	H-Area Tank Farm
ISI	In-Service Inspection Program
ITIVS	Independent Tank Integrity Verification Specialists
NDE	Nondestructive Examination
RBOF	Receiving Basin for Off-Site Fuels
SCDHEC	South Carolina Department of Health and Environmental Control
SRMC	Savannah River Mission Completion
SRR	Savannah River Remediation
SRS	Savannah River Site
UT	Ultrasonic Testing

1 Introduction

Since the site's design, construction, and startup in the 1950s, the primary mission of the Savannah River Site (SRS) had been to produce nuclear materials for the national defense and deep space missions. The processes used to recover many of these nuclear materials from production reactor fuel and target assemblies in the F- and H-Area chemical separations facilities (i.e., F Canyon and H Canyon) generated significant volumes of liquid radioactive waste. Today, over 34 million gallons of liquid radioactive waste is stored in 43 underground, carbon steel waste tanks. Many of these tanks are now over 60 years in age, having been constructed and placed into active service in the 1950's. In addition, many of these tanks lack full secondary containment and some have known leak sites in the primary tank walls. However, all tanks with known leak sites do have a secondary containment pan that is 5' in height that contains any leaked waste.

Savannah River Mission Completion LLC (SRMC), the liquid waste contractor at SRS, has implemented a robust structural integrity program for the waste tanks at SRS. In 2022, SRMC assumed the liquid waste contract. This program is designed to ensure the continued safe storage of the radioactive liquid waste by ensuring the tanks will not collapse, rupture, or fail during their operational life. As part of this structural integrity program, annual inspections are conducted on each of the 43 waste tanks in active service to ensure conditions have not degraded over time.

The purpose of this report is to summarize the results of these individual inspections, as well as Documented Safety Analysis (DSA) credited passive Safety Class/Safety Significant systems, that were conducted in calendar year 2021.

2 Requirements

The Department of Energy (DOE) requires SRMC to maintain a robust and timely structural integrity program for both tanks that are leak-tight and for tanks that have leaked or are suspect. These requirements are documented in DOE Manual 435.1-1, Section II.Q.(2). For tanks that are considered "Leak-Tight Tanks In-Service," a structural integrity program must be implemented that is capable of:

1. Verifying the current leak-tightness and structural strength of each tank in service;
2. Identifying corrosion, fatigue, and other critical degradation modes;
3. Adjusting the chemistry of tank waste, calibrating cathodic protection systems, wherever employed, and implementing other necessary corrosion protective measures;
4. Providing credible projections as to when structural integrity of each tank can no longer be assured; and
5. Identifying the additional controls necessary to maintain an acceptable operating envelope

The Corrosion Control Program (CCP), along with the In-Service Inspection Program (ISI), help satisfy these requirements.

Further, for tanks that are considered "In-Service Tanks that Have Leaked or Are Suspect," a modified structural integrity program must be implemented to "identify the safe operational

envelope.” In addition to the five elements listed above, the modified program for these tanks must be capable of:

6. Determining which of the tanks that have leaked or are suspect may remain in service by identifying an acceptable safe operating envelope.

This section also requires that the “structural integrity of other storage components shall be verified to assure leak tightness and structural strength.”

In *United States Department of Energy / Westinghouse Savannah River Company, Savannah River Site, Aiken, South Carolina, As-Built Construction Permit Application for an Industrial Wastewater Treatment Facility for the F and H-Area High-Level Radioactive Waste Tank Farms*, construction permit number 17,424-IW, dated April 1991, Section 1.6, Assessment and Inspections, it is noted for each waste tank system that did not meet secondary containment criteria described in Section IX.C of the SRS Federal Facility Agreement (FFA):

“... information is provided to demonstrate that these waste tank systems are adequately designed and have sufficient structural strength and compatibility with the hazardous and/or radioactive substances that will be stored or treated, to ensure that the waste tank system will not collapse, rupture, or fail.”

This section of the As-Built Construction Permit Application further states:

“In addition to the attached assessment report, annual inspection reports will be submitted to SCDHEC on or before July 1st of each year. These inspection reports will satisfy the requirements of Section IX.A.2 of the FFA for on-going demonstrations. These inspections will be conducted annually for each waste tank system until the waste tank system is removed from service.”

Section IX.A.2 of the FFA states, in pertinent part, the following:

“The permit applications submitted under Subsection A.1 above shall include a description of past leaks and demonstrations, subject to the review and approval of SCDHEC, that each high-level waste tank system is not leaking. The permit applications submitted by DOE under Subsection A.1 shall include proposed methods and a schedule for ongoing demonstrations that these tank system(s) are not leaking. Such methods and schedule shall be complied with until such time as the waste tank system(s) is removed from service under Subsection E herein.”

This report has been developed, in part, to fulfill the regulatory requirements for annual inspections of the waste tanks at SRS consistent with the provisions of the 17,424-IW permit. It should be noted that, as stated above, these annual inspections are only required for those tanks still in active service. Tanks 5, 6, 12, 16, 17, 18, 19 and 20 have been operationally closed and no longer require inspections under these requirements. Instead, as established in the Interim Record of Decision for each of these tanks, SRMC conducts annual viable engineered barriers inspections and performs any maintenance necessary as a result of these inspections.

3 Waste Tank Descriptions

There were 51 underground liquid radioactive waste storage tanks constructed and placed into service at SRS. Twenty-two waste tanks are in the F-Area Tank Farm (FTF) and 29 waste tanks

are in the H-Area Tank Farm (HTF). The main component of a waste tank is the primary liner, typically referred to as the primary tank, which is designed to contain the liquid waste and associated precipitated solids. The primary tanks are cylindrical and fabricated of welded carbon steel plates. There are four principal waste tank designs designated as Type I, II, III/IIIA, and IV.

The waste tanks were constructed during different time periods and design features were changed to incorporate improvements and lessons learned. Table 3-1 summarizes the FTF and HTF waste tank design types.

Table 3-1: Summary of SRS Waste Tank Design Types

Tank Number	Tank Farm	Design Type	Year Constructed	Type of Construction	Volume (gallons) ^a
1 – 8	F	I	1952	Double Wall-Cooled	750,000
9 – 12	H	I	1953	Double Wall-Cooled	750,000
13 – 16	H	II	1956	Double Wall-Cooled	1,070,000
17 – 20	F	IV	1958	Single Wall-Uncooled	1,300,000
21 – 24	H	IV	1961-1962	Single Wall-Uncooled	1,300,000
25 – 28	F	IIIA	1978	Double Wall-Cooled	1,300,000
29 – 32	H	III	1970	Double Wall-Cooled	1,300,000
33	F	III	1969	Double Wall-Cooled	1,300,000
34	F	III	1972	Double Wall-Cooled	1,300,000
35 – 43	H	IIIA	1976-1979	Double Wall-Cooled	1,300,000
44 – 47	F	IIIA	1980	Double Wall-Cooled	1,300,000
48 – 51	H	IIIA	1981	Double Wall-Cooled	1,300,000

^a Nominal Fill Capacity

3.1 Type I Tanks

There are eight Type I tanks in FTF (Tanks 1 through 8) and four Type I tanks in HTF (Tanks 9 through 12); all were constructed in the early 1950s as part of the original site construction activities. Tanks 5 and 6 in FTF were operationally closed in 2013 and Tank 12 in HTF was operationally closed in 2016. Figure 3.1-1 shows the Type I tanks during construction.


Figure 3.1-1: Construction of the Type I Tanks in FTF



Type I primary tanks have a 75-foot inside diameter and are 24 feet, 6 inches high with a nominal operating capacity of 750,000 gallons. [N-ESR-G-00001] The primary tank sits inside a 5-foot high, 79-foot 11-inch inside diameter secondary liner (also known as the annular pan). The primary tank and secondary liner are enclosed within an 83-foot, 8-inch outside diameter concrete vault that creates an approximately 2-foot, 5.5-inch wide annular space. The Type I vault roofs in both FTF and HTF are approximately 9 feet below grade.

A typical Type I tank cross-section is shown in Figure 3.1-2. [SRS-REG-2007-00002]


Figure 3.1-2: Typical Type I Tank Cross-Section



The Type I primary tank is constructed of 0.5-inch thick carbon steel. The tank wall is joined to the roof and floor with non-stress-relieved welded knuckle plates also made of carbon steel. It should be noted that none of the Type I tanks were post-weld heat treated to relieve stresses following construction. The secondary liner is made of 0.5-inch thick carbon steel. The top edge of the secondary liner has a reglet – an L-shaped carbon steel stiffener lip that is wrapped in lead and extends 6 inches perpendicularly inward from the liner edge with another 4-inch long section extending perpendicularly down from that edge. [W145367] The primary tank roof is supported by twelve 2-foot diameter columns.

The primary tank rests on a 3-inch thick layer of grout inside the secondary liner and the secondary liner sits on a 3-inch thick layer of grout on top of the concrete base mat (Figure 3.1-3).

Figure 3.1-3: Typical Type I Tank Floor Configuration




At the time of construction, all welds in the primary and secondary liners were radiographically inspected, defects were corrected, and the welds were rechecked radiographically. The welds in the flat bottoms of both the primary and secondary liners were vacuum-tested for leaks. Additionally, both the secondary liners and the primary tanks were hydrostatically tested. The water was maintained at full height in the primary tanks and secondary liners for 24 hours before inspection for leaks was made.

Access to the primary tank interior is limited to nine locations, and to the annular space at four locations, through riser pipes that extend through the concrete vault roof and up through the approximately 9 feet of soil. Each of the 13 riser pipes is capped at the top with a concrete shield plug. Each plug is typically provided with two 5-inch diameter ports equipped with removable plugs (unless equipment has been installed to support waste removal or tank closure activities).

The center plug port may provide access through three 4- to 8-inch diameter ports. Some of these ports provide access for inspections. Figure 3.1-4 shows a typical layout of the Type I tank riser locations.


Figure 3.1-4: Typical Type I Tank Access Area



3.2 Type II Tanks


The second generation of waste tanks, the Type II tanks, completed construction in 1956 soon after the Type I tanks were placed into service. They are similar in design concept to the Type I tanks, but with some notable differences. There were only four Type II tanks constructed, Tanks 13 through 16, and were built as a four-pack in the HTF. There are no Type II tanks in the FTF. Tank 16 was operationally closed in 2015. Figure 3.2-1 shows the Type II tanks during construction.

Figure 3.2-1: Construction of the Type II Tanks in HTF



The Type II primary tanks have an 85-foot inside diameter and are 27 feet high with a nominal operating capacity of 1,070,000 gallons. The primary tank sits inside a 5-foot high, approximately 90-foot, 1.25-inch inside diameter secondary liner. The primary tank and secondary liner (also known as the annular pan) are enclosed within a 95-foot, 8.5-inch outside diameter concrete vault that creates an approximately 2-foot, 6.625-inch wide annular space. Unlike the Type I tanks, these tanks were built so that the roof of the concrete vault was at grade level; this concrete roof is 3 feet, 9 inches thick. A typical Type II tank cross-section is shown in Figure 3.2-2.

Figure 3.2-2: Typical Type II Tank Cross-Section




The primary tank is made of 0.625-inch thick carbon steel. The tank wall is joined to the primary tank roof and floor with non-stress relieved welded knuckle plates also made of carbon steel. The top knuckle is 0.5625 inches thick; the bottom knuckle is 0.875 inches thick; and the associated top and bottom plates are 0.5 inches thick; all are made of carbon steel. It should be noted that none of the Type II tanks were post-weld heat treated to relieve stresses following construction. The secondary liner is made of 0.5-inch thick carbon steel. [W162688] The top edge of the secondary liner has a reglet – an L-shaped carbon steel stiffener lip that is wrapped in lead and extends 6 inches perpendicularly inward from the liner edge with another 4-inch long section extending perpendicularly down from that edge. The primary tank was constructed above a 1-inch thick sand pad placed on top of the secondary liner. An additional 1-inch thick sand pad is between the secondary liner and the base mat. Unlike the Type I tanks, the Type II tanks do not have a series of roof support columns. Instead, these tanks have a single, large roof support in the center of the tank.

At the time of construction, all welds in the primary tanks were radiographically inspected, defects were corrected, and the welds were rechecked radiographically. However, the secondary liners were not inspected radiographically. The welds in the flat bottoms of these liners and the primary tanks were vacuum-tested for leaks, and the primary tanks and secondary liners were hydrostatically tested.

Access to the primary tank interior is provided at eleven locations and, originally, to the annular spaces at four locations, through riser openings. Each of the original fifteen riser openings is capped at the top with a concrete plug. Each plug is provided with two 5-inch diameter ports equipped with removable plugs. The ports provide access for inspection. In addition to the original four annulus risers, other access openings (10 to 14 additional openings per tank) have been core-drilled into the annulus of each of these tanks to permit inspection of 89 to 96% of the exterior walls of the primary tanks. These supplemental inspection ports were added following the formation of numerous leak sites soon after each of these tanks began receiving and storing liquid radioactive waste from H Canyon. Figure 3.2-3 shows a typical layout of the original Type II tank riser locations prior to the addition of the supplemental inspection ports.

Figure 3.2-3: Typical Type II Tank Access Area




NOTE: Risers may be impeded by installed equipment.
[NOT TO SCALE]

Riser configuration at time of construction.

3.3 Type IV Tanks

The Type IV tanks are single-walled tanks that have no auxiliary cooling capability. These tanks were specifically designed to store waste that contained significantly lower concentrations of radioactive material. There are four Type IV tanks in FTF that were constructed during the late 1950s (Tanks 17 through 20) and four Type IV tanks in HTF that were constructed between 1958 and 1962 (Tanks 21 through 24). All four of the FTF Type IV tanks have been operationally closed – Tanks 17 and 20 in 1997, and Tanks 18 and 19 in 2012. Figure 3.3-1 shows the Type IV tanks during construction.

Figure 3.3-1: Construction of Type IV Tanks



Type IV tanks have a single carbon steel liner with a hemispherical, reinforced concrete roof. These tanks are 85 feet in diameter and approximately 34 feet high at the side wall with a nominal operating capacity of 1,300,000 gallons. The liner wall and floor are made of 0.375-inch thick carbon steel with 0.4375-inch thick knuckle plates. The liner wall is reinforced internally by three circumferential 4- by 4-inch, L-shaped, carbon steel stiffener bands. This liner is anchored externally to the enclosing concrete vault wall. The liner floor is essentially flat with no sump, significant low points, or slope.

The Type IV tank roof is a self-supporting, hemispherical dome made of 7- to 10-inch thick concrete. The dome has an internal curvature radius of 90 feet, 4 inches and a maximum rise of 10 feet, 7.5 inches above the springline. The tank roof is not lined with carbon steel on the inside.


Each Type IV tank wall is enclosed in concrete; this concrete was placed in layers using a shotcrete technique. The concrete wall is cylindrical with an inside diameter of 85 feet and a height of 34 feet, 3.75 inches at the springline surmounted by a dome ring. The concrete wall is 7-inches thick at the top and 11-inches thick at the bottom. This wall was prestressed with steel bands that remained in place and were covered with the concrete. Figure 3.3-2 shows these bands and associated turnbuckles prior to the formation of the concrete wall.

Figure 3.3-2: Steel Bands and Turnbuckles on the Type IV Tank Walls



There is no secondary containment (secondary liner) or an annulus in the Type IV tanks. Instead, drainage channels were formed in a 3-inch thick concrete topping layer above the basemat and drain to a collection point, which empties to a collection chamber (sump) below the waste tank footing at the edge of the waste tank wall in Tanks 21 through 24. The tank side wall collection system would collect leakage into a sump. A riser pipe to the surface enables a leak detection probe to be placed in both chambers for sampling of any liquid that was to accumulate. A typical Type IV tank cross-section is shown in Figure 3.3-3.


Figure 3.3-3: Typical Type IV Tank Cross-Section



All welds in the carbon steel liners were radiographically inspected. All of the welded liner-bottom seams and the upper seams of the knuckle rings were vacuum leak-tested. Prior to the backfilling/placement of surrounding soils, each tank was hydrostatically tested by filling with water to the normal fill height. These tanks remained filled with these non-radioactive solutions until it was to be placed in active waste storage.

Access to the interior of the HTF Type IV tanks is provided at six locations through perimeter riser pipes that are 2-foot in diameter and 5 feet long. The Type IV tanks in FTF had a center roof riser while those in HTF do not. Each riser opening is capped at the top with a concrete plug. Some of these risers provide access for inspection. There is no access to inspect the outside of the carbon steel liner as it is in direct contact with the surrounding concrete wall. Further, the outside of the concrete wall is covered in soil for shielding purposes. Figure 3.3-4 shows the typical access locations for a HTF Type IV tank.

Figure 3.3-4: Typical Type IV Tank Access Locations



NOTE: Risers may be impeded by installed equipment.
[NOT TO SCALE]

3.4 Type III/IIIA Tanks

The Type III/IIIA tank designs captured many of the lessons learned from the earlier waste tank design, construction, and operational histories. These tanks have full secondary containment and are essentially designed as a tank within a tank as shown in Figure 3.4-1. There are two Type III tanks and eight Type IIIA tanks in the FTF. There are four Type III tanks and 13 Type IIIA tanks in the HTF. The waste tank numbers, associated tank farm, and construction years are listed in Table 3-1.

There are relatively minor construction detail differences between Type III and IIIA tanks, but the major differences are related to the type of cooling coils used inside the primary tank and the design of the purge ventilation system.

Figure 3.4-1: Typical Construction of Type III/IIIA Tanks



The Type III/IIIA primary tank is 85 feet in diameter and 33 feet high with a nominal operating capacity of 1,300,000 gallons. Type III/IIIA tanks have both a center and outer annulus. The center annulus is formed between the primary tank wall and the roof support column. The primary tank is made of concentric carbon steel cylinders joined to circular top and bottom plates by curved knuckle plates. The top plate of the primary tank is 0.5 inches thick, the middle plate is 0.625 inches thick and the bottom plate is 0.875 inches thick; the top knuckle is 0.5 inches thick and the bottom knuckle is 0.875 inches thick. After construction, the Type III/IIIA primary liners were fully stress-relieved by heating to help prevent the nitrate-induced, stress corrosion cracking seen in both the Type I and Type II tanks. The Type III/IIIA secondary liner is 0.375-inch thick carbon steel and is the full height of the primary liner with a 90-foot, 1.75-inch outside diameter forming a 2-foot, 6-inch wide annular space between the primary tank and secondary liner. [W702700]

The primary tank sits on a bed of insulating material with a system of grooves radiating outward from the base of the central column so ventilating air can flow through the slots and any leakage from the primary tank bottom, or in the annulus around the center column, would flow to the

outer annulus. The Type III tanks have a 6-inch thick layer of insulating material with 1-inch deep by 2-inch wide grooves. [W236993] The Type IIIA tanks have an 8-inch thick layer of insulating material with 2-inch deep by 5-inch wide grooves.

Type III/III A tanks have an air ventilation/cooling system embedded in the center support column with supply ducts extending to the radial air grooves built into the insulating layer between the primary tank and secondary liner. Typical Type III and Type III A tank cross-sections are shown in Figures 3.4-2 and 3.4-3, respectively.

Figure 3.4-2: Typical Type III Tank Cross-Section





Figure 3.4-3: Typical Type IIIA Tank Cross-Section



All butt welds on the primary tanks were radiographically inspected, except welds on the horizontal roof surface. On the secondary liners of Tanks 29 through 34, all butt welds joining bottom plates, knuckle plates, and the lowest courses of center-column and outer-wall plates, were radiographically inspected. On all other Type III tanks, all plate welds in the secondary tanks were radiographically inspected. All defects were corrected, and the welds were rechecked radiographically.

The Quality Assurance Program included inspection of all radiographs by two independent groups of certified weld inspectors, and all radiographs were permanently stored for future reference. All spots on the inside or outside of the primary tanks and the inside of the secondary liners, where clips or lugs were removed and where other excisions were made, were examined by magnetic particle or liquid penetrant techniques and any defects were repaired.


All butt welds on the secondary liners were vacuum leak-tested. All welds in the bottom assemblies of the primary tanks, including knuckle rings and lowest course welds, were vacuum leak-tested before each bottom assembly was lowered into final position, and then tested a second time after the stress-relieving operation. A full hydrostatic test, the filling of each primary tank to a depth of 32 feet and allowing it to stand 48 hours, was conducted after stress relieving. No leaks were found by the hydrostatic tests.

The primary tank was post weld heat treated in place after all high temperature work, other than roof attachments, had been completed. Post weld heat treatment was accomplished in accordance with the general requirements of the ASME Boiler and Pressure Vessel code.

Tanks 29 through 34 were placed in service prior to 1976. These tanks were constructed with annulus riser openings at four locations providing inspection access through 5-inch diameter ports. All other Type III/IIIA tanks were placed in service after 1976 and have annulus riser

openings at 18 locations that are 8-inches in diameter. These ports are equidistant around the tank and provide for inspection of the entire exterior wall of the primary vessel. In 1982, 14 to 16 additional 8-inch diameter ports per tank were drilled in the tops of Tanks 29 through 34 to provide adequate access ports for inspection of the entire exterior wall of their primary vessels. All Type III tanks have interior riser openings at various locations that provide inspection access through ports with diameters ranging from 4 to 8 inches. All inspection access ports are equipped with removable plugs.

Figure 3.4-4: Typical Type III/IIIA Tank Access Locations



4 Inspection Program Description

4.1 Background

The waste tanks have differing types of containment and leak detection. The first 24 tanks constructed and placed into service (Types I, II, and IV) do not meet current standards for secondary containment and/or leak detection and some of these tanks have experienced leakage from their primary tanks into secondary containment. Eight of the 24 tanks have now been operationally closed. The 27 new style tanks (Type III/IIIA) meet the standards for secondary containment and/or leak detection.

The detection of leaked waste is based on two principles: disappearance of material from its primary location and appearance of material in a secondary location. At SRS, primary reliance is on the latter because the quantity of the waste detectable in an improper location is much less than that detectable by inventory change in a large tank (i.e., nominal capacities ranging from 0.75 to 1.3 million gallons). Although rigorous tank inventory surveillance is practiced, primary leak detection methods rely on automatic surveillance of those areas into which the leaked waste is most likely to migrate.

The annulus of each tank with secondary containment (i.e., Types I, II, and III/IIIA tanks) that remains in service is equipped with at least two single-point conductivity probes for leak detection. These probes are located near the bottom of the annulus and on opposite sides of the tank where possible. The single-wall tanks (i.e., Type IV tanks) are built on slabs with a network of leak collection channels that drain to a common sump. Sump levels are continuously monitored with alarm capability in control rooms. Besides the automatic surveillance, routine direct visual surveys are made in the annular spaces, and nonroutine direct visual surveys are made in primary tanks through risers and/or inspection ports in the roof.

In 1961-1962, following leakage of waste into the annuli of Tanks 9, 10, 14, and 16, the first remote imaging inspections were made of some tanks using a periscope, with random inspections continuing through 1970. A program was initiated in November 1971 to periodically inspect all waste tanks using remote visual imagery techniques to monitor for corrosion and other degradation, waste leakage, anomalies of any type, and to investigate process or equipment concerns.

Steel thickness measurements have been made periodically of the waste tanks using ultrasonic techniques to monitor for general corrosion. An analog-type instrument was used in 1967 and 1969 to measure the thickness of the primary wall of tanks with annuli. In 1972, a more precise instrument was put in service. About 24,000 measurements made over a period of 14 years (1972 through 1985) indicated that no general thinning trends of SRS tanks had occurred. Steel thickness measurements were resumed in 1994 using an updated ultrasonic testing (UT) system. The system was updated again in 2002 using improved technology to detect thinning, pitting, and cracks.

To date, the only visually observed, service-induced corrosion was in Tank 23, a tank with a unique service history. The upper wall interior surfaces show general corrosion with mild pitting. The pitting is broad, but shallow. Evaluation of this condition is documented in DPSPU-85-11-4. This tank was used to receive contaminated water from 244-H, the Receiving Basin for Off-Site Fuels (RBOF), and 245-H, the Resin Regeneration Facility. No increase in the pitting or general corrosion has been observed. The 244-H and 245-H facilities are out of service, and Tank 23 is now used to store dissolved salt solutions.

Inspections of waste tanks are complicated by factors such as radiation and radioactive contamination, remote operation as far as 40 feet below grade, and insertion of equipment through small, generally 5- to 8-inches in diameter, access openings. Inspection techniques to circumvent these difficulties have been developed, and yield quality visual images (photographic) and/or volumetric measurements (i.e., UT). The techniques include photographic systems, closed-circuit television systems, and ultrasonic systems to measure steel thickness, cracking, and pitting.

Waste tank inspection has been important in leak detection. The leak sites in 10 of 14 tanks have been discovered by direct visual inspection or by one of the remote inspection techniques. Since the inspection program was initiated in 1971, eight tanks were found to have leak sites that were not identified by the installed leak detection equipment. The waste evaporated to dryness, sealing the leak sites before any liquid reached a leak detection probe. The remote inspections identified the dry deposits of salt in the annuli and/or on the walls of these tanks.

The waste tank ISI Program is ongoing. This report gives results of the 2021 UT and visual inspection data and summarizes significant findings of UT and visual inspections for each waste tank.

4.2 Inspection Methods

Techniques have been developed for remote examination and evaluation of the waste tanks and waste tank ancillaries. For visual imaging, direct photography systems developed at SRS were the primary method used. Closed-circuit television systems were also used where direct photography was not possible or where these systems provided a more comprehensive examination. Only the direct photography systems will be described since the video systems are similar to systems used widely in industry.

Due to significant improvements and advantages of digital photography, a conversion was made from film to digital photography in 2007. Wide-angle direct photography was used for general inspections of tank annuli and the primary vessels. This technique surveys a large area of the tank and annulus floor in a single photograph.

Another direct photography technique was used for detailed inspections. This technique provides detailed views of the tank in a series of photographs.

4.3 Visual Imagery

The 2021 inspection program used two visual imagery techniques: photography and closed-circuit television. The primary inspection methods were direct photography techniques, e.g., making a series of photographs providing detailed views of the tank and wide-angle photography for obtaining overviews of large areas. Closed-circuit television systems were generally used to further investigate conditions found during scheduled inspections and to document conditions and troubleshoot process problems in tanks and ancillaries.

The inspection program's objective to continuously evaluate the waste tanks was satisfied in 2021 by photographic and video documentation. Inspections were made through all accessible annulus risers of the Type I, II, and III/IIIA tanks and at least one inspection was made in the interior of each Type IV tank (i.e., Tanks 21 – 24).

For Tanks 1 through 4 and 7 through 11, inspections are limited to no more than 25% of the exterior of the primary vessel wall and the annular space due to limited annulus access. These tanks are monitored for leakage by instrumentation or cameras that can be installed in their annuli. Due to early leak site occurrences in the Type II tanks, Tanks 13 through 15 had additional inspection ports installed in their annuli allowing greater access and larger visual inspection capabilities.

Additionally, for those tanks that have known leak sites in the primary vessel and are not undergoing waste removal, the supernate phase has been removed, minimized, or the level lowered below the level of known leak sites.

5 Calendar Year 2021 Inspection Program Results

5.1 Overview

The 2021 inspection program was successfully completed. The annuli of all Type I, II, and III/IIIA tanks were inspected via all accessible risers and the interiors of the Type IV tanks remaining in service were inspected. Other inspections of waste tanks and ancillaries were performed as required by operating conditions and equipment performance requirements.

In addition to the waste tank ISI Program, the Structural Integrity program requires inspections/measurements to be performed on DSA credited passive safety equipment to ensure that the structural configuration and condition will allow the equipment to perform its intended design function under operational and accident conditions. The Structural Integrity program principally involves periodic visual and non-destructive inspection and test activities of safety equipment, concentrating on structural (i.e., passive) aspects of active and passive components. Equipment inspection frequency ranges from two to ten years, based on materials of construction, operating environment, etc. Equipment and systems that are physically accessible are evaluated through visual walk downs by a Structural Integrity subject matter expert and those that are inaccessible for walk down are inspected remotely by camera or video equipment. All inspections in 2021 were satisfactory with no material degradation noted that would prevent the equipment from performing its credited function. The following equipment scheduled for 2021 requiring physical walkdown inspection were completed.:

- T-DS-G-00026, HDB-8 Process Vessel Ventilation System
- T-DS-G-00027, HDB-8 Diesel Generator
- T-DS-G-00056, Tank 48 Oxygen Analyzers
- T-DS-G-00057, Normal Nitrogen System
- T-DS-G-00065, 242-25H Evaporator Primary Ventilation System

Ultrasonic nondestructive examinations scheduled for 2021 were performed in Tanks 47, 48 and 51. Inspections performed in Tanks 25 and 41 were per the Corrosion Control Program. The findings are documented in ITIVS-ISI-FY2021, *Tank Inspection NDE Results for Fiscal Year 2021, Waste Tanks 25, 41, 47, 48 and 51*, September 28, 2021, Revision 0.

Rainwater continues to periodically be observed leaking into the annulus of some tanks. Inleakage, which is water migrating into the annulus, was evidenced primarily by surface stains, occasionally by calciferous deposits, changed configuration of salt deposits in the annulus, and mild surface corrosion. The conditions of the tanks remained essentially unchanged from the conditions reported in 2020 with the exception of the two new cracks identified in the primary vessel wall of Tank 10. **The 2021 inspection program confirmed the structural integrity and waste confinement capability of all 43 waste tanks that remain in active service.**

Specific details and results for inspections of the tanks and ancillaries performed in 2021 are listed in Appendix A.

5.2 Tank Inspection Summary Sheets

Tank Inspection Summary Sheets are provided on the following pages for the 43 tanks that remain in active service. The sheets are designed to reflect the most recent information and build from the previous annual structural integrity reports. Sheets for the eight tanks that have been grouted and operationally closed (Tanks 5, 6, 12, 16,17, 18, 19, and 20) are not included. The individual tank sheets provide concise structural integrity-related information for each tank and a diagram of each tank type to depict inspection camera accessible locations. [NOTE: The status of the Type I, II, and IV tanks, the tanks that do not meet current requirements for secondary containment, are reported in SRR-ESH-2022-00019, Revision 0, *Status of F/H Area Radioactive Liquid Waste Tanks Being Removed from Service - CY2021 Annual Report.*]


Tank 1

Placed into Service

1954

- Type I Tank
- F Tank Farm

Annulus Inspection Location



Annulus Risers Available for Inspection: 3

Inspection Capability: 19%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
≥ 1	Feb 1969	Small deposits on floor	Unknown	Unknown

Last Visual Inspections: December 2021.

Summary of Visual Inspections: No changes were noted since the inspections in 2020.

Ultrasonic Testing Inspections Performed: 1978, 1979, 1981, 1983, and 1985

Ultrasonic Testing Inspections Results: No detectable thinning of tank wall.

Conclusions following 2021 Inspections: **No additional leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 1.**


Tank 2

Placed into Service

1955

- **Type I Tank**
- **F Tank Farm**

Annulus Inspection Location



Annulus Risers Available for Inspection: 4

Inspection Capability: 25%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: October 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1967, 1972, 1973, 1977, 1981, and 1985

Ultrasonic Testing Inspections Results: No detectable thinning of tank wall.


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 2.**

Tank 3

Placed into Service

1956

- **Type I Tank**
- **F Tank Farm**



Annulus Risers Available for Inspection: 4

Inspection Capability: 25%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: October 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1973, 1977, 1981, and 1985

Ultrasonic Testing Inspections Results: No detectable thinning of tank wall.

Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 3.**


Tank 4

Placed into Service

1961

- **Type I Tank**
- **F Tank Farm**

Annulus Inspection Location



Annulus Risers Available for Inspection: 4

Inspection Capability: 25%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
4	Oct 2011	None	South	234 in.
	Sep 2013	None	North	234 in.
	Sep 2013	None	North	234 in.
	Sep 2013	None	North	234 in.

Last Visual Inspections: November 2021.

Summary of Visual Inspections: No changes were noted since the inspections in 2020.

Ultrasonic Testing Inspections Performed: 1973, 1977, 1981, and 1985

Ultrasonic Testing Inspections Results: No detectable thinning of tank wall.

Conclusions following 2021 Inspections: **No leakage, significant surface corrosion or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 4.**


Tank 7

Placed into Service

1954

- **Type I Tank**
- **F Tank Farm**

Annulus Inspection Location



Annulus Risers Available for Inspection: 3

Inspection Capability: 19%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: October 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1974, 1979, 1981, 1983, and 1985

Ultrasonic Testing Inspections Results: No detectable thinning of tank wall.

Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 7.**


Tank 8

Placed into Service

1956

- **Type I Tank**
- **F Tank Farm**

Annulus Inspection Location



Annulus Risers Available for Inspection: 4

Inspection Capability: 25%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: November 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1973, 1977, 1981, and 1985

Ultrasonic Testing Inspections Results: No detectable thinning of tank wall.

Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 8.**


Tank 9

Placed into Service

1955

- **Type I Tank**
- **H Tank Farm**

Annulus Inspection Location



Annulus Risers Available for Inspection: 3

Inspection Capability: 19%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
≥ 4	Oct 1957	8-10 in. of salt deposits – 3 identified leak sites are not the source of the salt deposits in the annulus pan; source has not been identified	West West South Unknown	276 in. 271 in. 269 in. Source of waste in pan unknown

Last Visual Inspections: November 2021.

Summary of Visual Inspections: No changes were noted since the inspections in 2020.

Ultrasonic Testing Inspections Performed: 1979 and 1983

Ultrasonic Testing Inspections Results: No detectable thinning of tank wall.

Conclusions following 2021 Inspections: **No additional significant surface corrosion or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 9.**


Tank 10

Placed into Service

1955

- Type I Tank
- H Tank Farm

Annulus Inspection Location



Annulus Risers Available for Inspection: 3

Inspection Capability: 19%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
≥ 3	Jul 1959	2-3 in. of salt deposits – source of waste has not been identified	Unknown	Unknown
	2021		SE NNW	129" 110"

Last Visual Inspections: December 2021.

Summary of Visual Inspections: Two previously undocumented leak sites were identified in 2021.

Ultrasonic Testing Inspections Performed: 1979 and 1983

Ultrasonic Testing Inspections Results: No detectable thinning of tank wall.

Conclusions following 2021 Inspections: **No additional significant surface corrosion or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 10. Evaluation of newly identified leak sites are documented in SRR-LWE-2021-00166 and SRR-LWE-2022-00001.**


Tank 11

Placed into Service

1955

- **Type I Tank**
- **H Tank Farm**

Annulus Inspection Location



Annulus Risers Available for Inspection: 4

Inspection Capability: 25%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
2	Apr 1974	Salt nodules on wall of primary tank and trace amounts in annulus pan	West South	235 in. 189 in.

Last Visual Inspections: December 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1973, 1977, 1981, and 1985

Ultrasonic Testing Inspections Results: No detectable thinning of tank wall.


Conclusions following 2021 Inspections: **No additional significant surface corrosion or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 11.**

Tank 13

Placed into Service

1956

- Type II Tank
- H Tank Farm



Annulus Inspection Ports Available: 12

Inspection Capability: 90%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
3	Mar 1977	Salt nodules on wall of primary tank and trace amounts in annulus pan	West	279 in.
	May 1980	Salt nodules on wall of primary tank and trace amounts in annulus pan	North	269 in.
	Oct 2012	Salt nodules on wall of primary tank and trace amounts in annulus pan	West	270 in.

Last Visual Inspections: October 2021.

Summary of Visual Inspections: No changes were noted since the inspections in 2020.

Ultrasonic Testing Inspections Performed: 1974, 1979, 1985, and 2000

Ultrasonic Testing Inspections Results: No detectable thinning of tank wall.


Conclusions following 2021 Inspections: **No additional significant surface corrosion or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 13.**

Tank 14

Placed into Service

1957

- **Type II Tank**
- **H Tank Farm**



Annulus Inspection Ports Available: 13

Inspection Capability: 89%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
~50	May 1959 – 1974 Oct 2012	12-13 in. of salt deposits	Majority on bottom weld	Lowest 16 in. Highest 288 in.

Last Visual Inspections: October 2021.

Summary of Visual Inspections: No changes were noted since the inspections in 2020.

Ultrasonic Testing Inspections Performed: 1979 and 1983

Ultrasonic Testing Inspections Results: No detectable thinning of tank wall.

Conclusions following 2021 Inspections: **No additional significant surface corrosion or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 14.**

Tank 15


(Page 1 of 2)

Placed into Service

1960

- Type II Tank
- H Tank Farm

Annulus Inspection Locations



Annulus Inspection Ports Available: 14

Inspection Capability: 96%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location*	Elevation from Tank Bottom
34	Apr-72	Nodules on tank wall	140	34 in.
	Apr-72		144	34 in.
	1973	Waste on annulus floor	13	150 in.
	1973		115	88 in.
	1973		112	30 in.
	1973		105	96 in.
	1973		102	30 in.
	1973		171	74 in.
	1973		176	30 in.
	1973		173	30 in.
	1973		171	150 in.
	1973		136	34 in.
	1973		165	150 in.
	1997		207	150 in.
	1998		192	150 in.
	1997		53	200 in.
	2000		50	30 in.
	2000		205	30 in.
	2002 UT		175	129 in.
	2005		211	31 in.
	2015		5	73 in.
	2015		205	100 in.
	2015		5	92 in.
	2015		171	126 in.
	2017		99	30 in.
	2017		20	160 in.
	2018		239	152 in.
	2018		225	150 in.
	2018		238	76 in.
	2018		238	70 in.
	2018	82	200 in.	
	2018	82	176 in.	
	2018	238	65 in.	
	2018	238	67 in.	

*Circumferential feet clockwise from South riser.

Tank 15

(Page 2 of 2)

Placed into Service

1960

- **Type II Tank**
- **H Tank Farm**


Last Visual Inspections: October 2021.

Summary of Visual Inspections: No changes were noted since the inspections in 2020.

Ultrasonic Testing Inspections Performed: 1972, 1977, 1980, 1984, 2002, 2007, and 2015

Ultrasonic Testing Inspections Results: UT examinations in 2002 revealed a new leak site at 150 inches on the middle circumferential weld and four partial through wall cracks. [WSRC-TR-2002-00590] In 2007, UT examinations showed no reportable thinning or pitting areas on the tank wall. Ten cracks that were examined in 2002 were reexamined in 2007 with four cracks showing growth. Evaluations concluded the cracks would remain stable under bounding future waste loading conditions. [SRNS-STI-2008-00028] In 2015, eight of these cracks were again reexamined; four cracks showed growth within expected ranges and four showed no changes. [SRNL-STI-2015-00421].

Conclusions following 2021 Inspections: **No significant surface corrosion or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 15.**




Tank 21

Placed into Service

1961

- **Type IV Tank**
- **H Tank Farm**



Exposed Wall Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: Northeast riser in May 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020. Examination of concrete dome did not reveal any degradation; continues to meet ACI 318-95 code requirements.

Ultrasonic Testing Inspections Performed: 1973, 1977, 1980, and 1983

Ultrasonic Testing Inspections Results: No detectable thinning of tank liner bottom.

Conclusions following 2021 Inspections: **No inleakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 21.**


Tank 22

Placed into Service

1965

- **Type IV Tank**
- **H Tank Farm**

In-Tank Inspection Location



Exposed Wall Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: December 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020. Examination of concrete dome did not reveal any degradation; continues to meet ACI 318-95 code requirements.

Ultrasonic Testing Inspections Performed: 1974, 1977, 1980, and 1983

Ultrasonic Testing Inspections Results: No detectable thinning of the tank liner bottom.

Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 22.**


Tank 23

Placed into Service

1964

- **Type IV Tank**
- **H Tank Farm**

In-Tank Inspection Location



Exposed Wall Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: Southwest riser in November 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020. Visual examinations of the steel liner have revealed corrosion, including rust and tubercles on the surface of the upper position of liner wall, but there is no evidence of failure. Broad and shallow pitting was observed. Examination of concrete dome did not reveal any degradation; continues to meet ACI 318-95 code requirements.

Ultrasonic Testing Inspections Performed: 1973, 1977, 1980, and 1983

Ultrasonic Testing Inspections Results: No detectable thinning of the liner bottom.


Conclusions following 2021 Inspections: **No inleakage, additional surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 23.**

Tank 24

Placed into Service

1963

- Type IV Tank
- H Tank Farm



Exposed Wall Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: Southeast riser in May 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020. Examination of concrete dome did not reveal any degradation; continues to meet ACI 318-95 code requirements.

Ultrasonic Testing Inspections Performed: 1984

Ultrasonic Testing Inspections Results: No detectable thinning of tank liner.


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 24.**

Tank 25

Placed into Service

1980

- **Type IIIA Tank**
- **F Tank Farm**



Annulus Inspection Ports Available: 18

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: August 2021

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1979, 1983, 2004, 2011, 2019, and 2021.

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. [ITIVS-ISI-FY2021]


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 25.**

Tank 26

Placed into Service

1980

- **Type IIIA Tank**
- **F Tank Farm**



Annulus Inspection Ports Available: 18

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: November 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1979, 1983, 2003, 2011, 2014, and 2019

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. [SRNL-STI-2019-00519]


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 26.**

Tank 27

Placed into Service

1980

- Type IIIA Tank
- F Tank Farm



Annulus Inspection Ports Available: 18

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: December 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1979, 1983, 2005, and 2014

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. [SRNL-STI-2014-00328]


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 27.**

Tank 28

Placed into Service

1980

- **Type IIIA Tank**
- **F Tank Farm**



Annulus Inspection Ports Available: 18

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: August 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1979, 1983, 2005, and 2014

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. [SRNL-STI-2014-00328]


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 28.**

Tank 29

Placed into Service

1971

- **Type III Tank**
- **H Tank Farm**



Annulus Inspection Ports Available: 18

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: September 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1973, 1974, 2006, 2009, and 2018

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. Incipient pitting was detected in several locations, with the deepest pit measuring 0.063" deep. [SRNL-STI-2018-00457]


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 29.**

Tank 30

Placed into Service

1974

- Type III Tank
- H Tank Farm



Annulus Inspection Ports Available: 18

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: November 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1975, 2003, 2010, and 2018

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. Ten incipient pits were documented; however, all of the pits are consistent with pre-service pitting with no evidence of active corrosion or growth. [SRNL-STI-2018-00457]


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 30.**

Tank 31

Placed into Service

1972

- **Type III Tank**
- **H Tank Farm**



Annulus Inspection Ports Available: 18

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: October 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 2003, 2010, and 2018

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. Nine incipient pits were documented; however, all of the pits are consistent with pre-service pitting with no evidence of active corrosion or growth. [SRNL-STI-2018-00457]


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 31.**

Tank 32

Placed into Service

1971

- **Type III Tank**
- **H Tank Farm**



Annulus Inspection Ports Available: 19

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: November 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 2003, 2010, and 2018

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. Seven incipient pits were documented; however, all of the pits are consistent with pre-service pitting with no evidence of active corrosion or growth. [SRNL-STI-2018-00457]


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 32.**

Tank 33

Placed into Service

1969

- **Type III Tank**
- **F Tank Farm**



Annulus Inspection Ports Available: 20

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: October 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 2005, 2014, and 2019

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. [SRNL-STI-2019-00519]

Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 33.**


Tank 34

Placed into Service

1972

- **Type III Tank**
- **F Tank Farm**

Annulus Inspection Locations



Annulus Inspection Ports Available: 20

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: October 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 2003, 2011, and 2019

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. [SRNL-STI-2019-00519]


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 34.**

Tank 35

Placed into Service

1977

- **Type IIIA Tank**
- **H Tank Farm**



Annulus Inspection Ports Available: 18

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: September 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1977, 1981, 1985, 2006, and 2017

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. [SRNL-STI-2017-00539]


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 35.**

Tank 36

Placed into Service

1977

- **Type IIIA Tank**
- **H Tank Farm**



Annulus Inspection Ports Available: 18

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: September 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1977, 1981, 1985, 2007, and 2017

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. [SRNL-STI-2017-00539]


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 36.**

Tank 37

Placed into Service

1978

- Type IIIA Tank
- H Tank Farm



Annulus Inspection Ports Available: 18

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: December 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1977, 1981, 1985, 2007, and 2017

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. [SRNL-STI-2017-00539]


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 37.**

Tank 38

Placed into Service

1981

- **Type IIIA Tank**
- **H Tank Farm**



Annulus Inspection Ports Available: 18

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: September 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1980, 1981, 1984, 2007, and 2017

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. [SRNL-STI-2017-00539]


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 38.**

Tank 39

Placed into Service

1982

- **Type IIIA Tank**
- **H Tank Farm**



Annulus Inspection Ports Available: 18

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: June 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1980, 1981, 1984, 1985, 2005, and 2016

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. Several grinding areas in the upper plate of the primary tank wall had areas below the 10% reporting criteria. [SRNL-STI-2016-00454]


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 39.**

Tank 40

Placed into Service

1986

- **Type IIIA Tank**
- **H Tank Farm**



Annulus Inspection Ports Available: 18

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: December 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1980, 1981, 1984, 2006, and 2016

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. Reportable thicknesses were detected in the top plate of the primary tank wall but were attributed to fabrication artifacts. [SRNL-STI-2016-00454]


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 40.**

Tank 41

Placed into Service

1982

- **Type IIIA Tank**
- **H Tank Farm**



Annulus Inspection Ports Available: 18

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: November 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1980, 1981, 1984, 2006, 2010, 2016, 2019 and 2021.

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. [ITIVS-ISI-FY2021]


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 41.**

Tank 42

Placed into Service

1982

- **Type IIIA Tank**
- **H Tank Farm**



Annulus Inspection Ports Available: 18

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: October 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1980, 1981, 1984, 1985, 1990, 2004, and 2015

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. [SRNL-STI-2015-00421]


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 42.**

Tank 43

Placed into Service

1982

- Type IIIA Tank
- H Tank Farm



Annulus Inspection Ports Available: 18

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: September 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1980, 1981, 1984, 1985, 2006, and 2015

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. Reportable thicknesses were detected in the top and middle plates of the primary tank but are attributed to fabrication artifacts. [SRNL-STI-2015-00421]


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 43.**

Tank 44

Placed into Service

1982

- Type IIIA Tank
- F Tank Farm



Annulus Inspection Ports Available: 18

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: August 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1980, 1981, 1984, 2005, 2013, and 2020

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. [SRNL-STI-2020-00396]


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 44.**

Tank 45

Placed into Service

1982

- Type IIIA Tank
- F Tank Farm



Annulus Inspection Ports Available: 18

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: July 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1980, 1981, 1984, 2005, 2013, and 2020

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. [SRNL-STI-2020-00396]

Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 45.**


Tank 46

Placed into Service

1980

- Type IIIA Tank
- F Tank Farm

Annulus Inspection Locations



Annulus Inspection Ports Available: 18

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: July 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1980, 1981, 1984, 2005, 2013, and 2020

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. [SRNL-STI-2020-00396]


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 46.**

Tank 47

Placed into Service

1980

- **Type IIIA Tank**
- **F Tank Farm**



Annulus Inspection Ports Available: 18

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: July 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1980, 1981, 1984, 2005, 2013, and 2021

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. An incipient pit was noted in the lower plate of the primary tank wall. [ITIVS-ISI-FY2021]


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 47.**

Tank 48

Placed into Service

1983

- **Type IIIA Tank**
- **H Tank Farm**



Annulus Inspection Ports Available: 18

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: March 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1982, 2004, 2012, and 2021

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. [ITIVS-ISI-FY2021]


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 48.**

Tank 49

Placed into Service

1983

- **Type IIIA Tank**
- **H Tank Farm**



Annulus Inspection Ports Available: 18

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: August 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1982, 2004, and 2012

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. [SRNL-STI-2012-00749]


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 49.**

Tank 50

Placed into Service

1983

- **Type IIIA Tank**
- **H Tank Farm**



Annulus Inspection Ports Available: 18

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: August 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1982, 2004, and 2012

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. [SRNL-STI-2012-00749]


Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 50.**

Tank 51

Placed into Service

1986

- **Type IIIA Tank**
- **H Tank Farm**



Annulus Inspection Ports Available: 18

Inspection Capability: 100%

Number of Known Leak Sites	Date of Discovery	Waste on Annulus Floor	Location	Elevation from Tank Bottom
No known leak sites	n/a	n/a	n/a	n/a

Last Visual Inspections: November 2021.

Summary of Visual Inspections: No areas of concern since last evaluated in 2020.

Ultrasonic Testing Inspections Performed: 1982, 2004, 2012, and 2021.

Ultrasonic Testing Inspections Results: No reportable thinning, pitting or stress corrosion cracking, or evidence of service-induced tank wall thinning on the primary tank wall. [ITIVS-ISI-FY2021]

Conclusions following 2021 Inspections: **No leakage, significant surface corrosion, or other anomalies were noted. The 2021 inspection confirmed the structural integrity and waste confinement capability of Tank 51.**

6 Conclusion

The conditions of the 43 in-service tanks remained essentially unchanged from the conditions reported in 2020. One key exception was the identification of two new cracks in the Tank 10 primary tank wall. These newly discovered cracks were located at 110 and 129 inches above the tank bottom. The 2021 inspection program confirmed the structural integrity and waste confinement capability of all 43 waste tanks currently in service for waste storage at SRS.

7 References

DPSPU-85-11-4, Jenkins, C.F., and Bird, P.S., *Dye Penetrant Inspections of Internal Walls, Waste Tanks 17, 20, 23, March-July 1984*, Revision 0, DuPont Savannah River Plant, Aiken, SC, September 1985.

ITIVS-ISI-FY2021, Elder, J.B. and Vande Kamp, R.W., Tank Inspection NDE Results for Fiscal Year 2021, Waste Tanks 25, 41, 47, 48 and 51.

N-ESR-G-00001, Williams, F.L., *High Level Waste Emergency Response Data and Waste Tank Data*, Revision 848, Savannah River Remediation, Aiken, SC, July 2018.

SRNL-STI-2012-00749, Elder, J.B. and Vande Kamp, R.W., *Tank Inspection NDE Results for Fiscal Year 2012, Waste Tanks 48, 49, 50 and 51*, Revision 0, Savannah River National Laboratory, Aiken, SC, January 2013.

SRNL-STI-2014-00328, Elder, J.B. III and Vande Kamp, R.W., *Tank Inspection NDE Results for Fiscal Year 2014, Waste Tanks 26, 27, 28 and 33*, Revision 0, Savannah River National Laboratory, Aiken, SC, August 2014.

SRNL-STI-2015-00421, Elder, J.B. III, and Vande Kamp, R.W., *Tank Inspection NDE Results for Fiscal Year 2015, Waste Tanks 42, 43, and 15*, Revision 0, Savannah River National Laboratory, Aiken, SC, September 2015.

SRNL-STI-2016-00454, Elder, J.B. III, and Vande Kamp, R.W., *Tank Inspection NDE Results for Fiscal Year 2016, Waste Tanks 39, 40, and 41*, Revision 0, Savannah River National Laboratory, Aiken, SC, September 2016.

SRNL-STI-2017-00539, Elder, J.B. III, and Vande Kamp, R.W., *Tank Inspection NDE Results for Fiscal Year 2017, Waste Tanks 35, 36, 37, and 38*, Revision 0, Savannah River National Laboratory, Aiken, SC, November 2017.

SRNL-STI-2018-00457, Elder, J.B. III, and Vande Kamp, R.W., *Tank Inspection NDE Results for Fiscal Year 2018, Waste Tanks 29, 30, 31, and 32*, Revision 0, Savannah River National Laboratory, Aiken, SC, October 2018.

SRNL-STI-2019-00519, Elder, J.B. III, and Vande Kamp, R.W., *Tank Inspection NDE Results for Fiscal Year 2019, Waste Tanks 25, 26, 33, 34, 41 and 50*, Revision 0, Savannah River National Laboratory, Aiken, SC, October 2019.

SRNL-STI-2020-00396, Elder, J.B. III, and Vande Kamp, R.W., *Tank Inspection NDE Results for Fiscal Year 2020, Waste Tanks 44, 45 and 46*, Revision 0, Savannah River National Laboratory, Aiken, SC, October 29, 2020.

SRNS-STI-2008-00028, Wiersma, B.J., and Elder, J.B., *A Structural Impact Assessment of Flaws Detected During Ultrasonic Examination of Tank 15*, Revision 0, Savannah River National Laboratory, Aiken, SC, August 2008.

SRR-ESH-2022-00019, Liner, K. R., *Status of F/H Area Radioactive Liquid Waste Tanks Being Removed from Service CY2021 Annual Report*, Revision 0, Savannah River Remediation, Aiken, SC, March 2022.

SRR-LWE-2021-00166, Waltz, R. S., *Evaluation of Indication on Primary Tank Wall at Tank 10*, Revision 0, Savannah River Remediation, Aiken, SC, December 2021.

SRR-LWE-2022-00001, Waltz, R. S., *Evaluation of Indication on Primary Tank Wall at Tank 10 North Riser*, Revision 0, Savannah River Remediation, Aiken, SC, January 2022.

SRS-REG-2007-00002, *Performance Assessment for F-Tank Farm at the Savannah River Site*, Revision 1, Savannah River Remediation, Aiken, SC, March 2010.

T-DS-G-00026, *Structural Integrity (S.I.) Data Sheet*, Revision 4, May 2020.

T-DS-G-00027, *Structural Integrity (S.I.) Data Sheet*, Revision 4, May 2020.

T-DS-G-00056, *Structural Integrity (S.I.) Data Sheet*, Revision 2, August 2016.

T-DS-G-00057, *Structural Integrity (S.I.) Data Sheet*, Revision 2, September 2016.

T-DS-G-00065, *Structural Integrity (S.I.) Data Sheet*, Revision 1, May 2020.

W145367, *Savannah River Plant 200 Area Waste Storage Tanks 241-F and H Steel Pan Plate Details Steel*, Revision 1, July 1954.

W162688, *Waste Storage Tanks Pan for 85'-0" Diam Tank – Plate Details*, Revision 14, August 1955.

W236993, *Savannah River Plant 200 Area Bldg 241H High Level Waste Storage Facilities Cooling Slots, Plans & Details Steel*, Revision 8, April 2015.

W702700, *Additional Waste Storage Tanks Cooling Slots Plan & Details*, Revision 7, September 1977.

WSRC-TR-2002-00590, Wiersma, B.J., *A Structural Impact Assessment of Flaws Detected During Ultrasonic Examination of Tank 15*, Revision 0, Westinghouse Savannah River Company, Aiken, SC, March 2003.

Appendix A – Summary of 2021 Inspection

Acronyms

A	Annulus
CCTV	Closed Circuit Television
COP	Clean Out Port
DB	Diversion Box
DP	Direct Photography
DSP	Digital Still Photograph
ERIP	Encasement Riser Inspection
EVAP	Evaporator
FLWB	Flushwater Box
GDL	Gravity Drain Line
HLLCP	High Liquid Level Conductivity Probe
I	Interior
IAL	Inter-Area Line
LDB	Leak Detection Box
PP	Pump Pit
STP	Submersible Transfer Pump
VB	Valve Box
WAP	Wide Angle Photography
WLE	Waste Line Encasement

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
F	01	East (A)	12/12/21	DP	/ P21281:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 11/20/20.
F	01	East (A)	12/12/21	DP	/ P21281:18	The magnetically mounted tank wall thermocouple was properly positioned.
F	01	North (A)	12/12/21	DP	/ P21282:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 11/20/20.
F	01	North (A)	12/12/21	DP	/ P21283:01-21	Remote visual inspection of the secondary vessel wall revealed no changes since last evaluated on 11/01/17.
F	01	West (A)	12/12/21	DP	/ P21280:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 11/22/20.
F	02	East (A)	10/25/21	DP	/ P21204:01-20	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 09/26/20.
F	02	East (A)	10/25/21	DP	/ P21204:18	The magnetically mounted tank wall thermocouple was properly positioned.
F	02	East (A)	10/25/21	DP	/ P21205:01-20	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 09/02/17.
F	02	North (A)	10/24/21	WAP	/ P21201:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 09/26/20.
F	02	South (A)	10/25/21	DP	/ P21206:01-20	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 09/26/20.
F	02	West (A)	10/24/21	WAP	/ P21201:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 09/26/20.
F	03	East (A)	10/27/21	DP	/ P21209:01-21	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 09/27/20.
F	03	East (A)	10/27/21	DP	/ P21210:01-20	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 12/03/18.
F	03	North (A)	11/02/21	DP	/ P21214:01-19	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 09/26/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
F	03	North (A)	11/02/21	DP	/ P21215:01-17	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 09/02/17.
F	03	South (A)	10/27/21	DP	/ P21211:01-20	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 09/27/20.
F	03	West (A)	10/27/21	DP	/ P21212:01-19	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 09/27/20.
F	03	West (A)	10/27/21	DP	/ P21212:18	The magnetically mounted tank wall thermocouple was properly positioned.
F	04	VB-02	08/08/21	CCTV	/ V210478	Inspection of the stainless steel liner, conductivity probe, jumpers and valves was satisfactory per SW11.6-SVP-45, Section 7.9.
F	04	East (A)	11/04/21	DP	/ P21220:18	The magnetically mounted tank wall thermocouple was properly positioned.
F	04	East (A)	11/04/21	DP	/ P21220:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 10/10/20.
F	04	North (A)	11/09/21	CCTV	/ V210641	Remote visual tank wall inspection revealed no changes since evaluated on 10/16/20.
F	04	South (A)	11/04/21	DP	/ P21222:01-20	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 10/05/19.
F	04	South (A)	11/04/21	DP	/ P21221:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 10/10/20.
F	04	West (A)	11/04/21	DP	/ P21223:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 10/10/20.
F	05	VB-01	08/08/21	CCTV	/ V210478	Inspection of the stainless steel liner, cover, jumpers, conductivity probe and valves was satisfactory per SW11.6-SVP-45, Section 7.9.
F	06	VB-03	08/08/21	CCTV	/ V210478	Inspection of the stainless steel liner, conductivity probe, jumpers and valves was satisfactory per SW11.6-SVP-45, Section 7.9.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
F	07	North (A)	10/25/21	DP	/ P21207:01-20	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 10/08/20.
F	07	South (A)	10/24/21	WAP	/ P21202:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 10/08/20.
F	07	West (A)	10/25/21	DP	/ P21208:01-20	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 10/08/20.
F	07	West (A)	10/25/21	DP	/ P21208:17	The magnetically mounted tank wall thermocouple was properly positioned.
F	08	LDB-17	12/17/21	CCTV	/ V210766	Remote visual inspection of cover, stainless steel liner, conductivity probe, jumpers, valves and piping was satisfactory per SW11.6-SVP-45, Section 7.9.
F	08	VB-04	08/08/21	CCTV	/ V210478	Inspection of the stainless steel liner, cover, jumpers and valves was satisfactory per SW11.6-SVP-45, Section 7.9.
F	08	East (A)	11/02/21	DP	/ P21217:01-20	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 10/07/20.
F	08	East (A)	11/02/21	DP	/ P21217:18	The magnetically mounted tank wall thermocouple was properly positioned.
F	08	East (A)	11/02/21	DP	/ P21218:01-17	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 06/12/16.
F	08	North (A)	11/02/21	DP	/ P21216:01-20	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 09/26/20.
F	08	South (A)	11/02/21	DP	/ P21219:01-20	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 09/26/20.
F	08	West (A)	10/24/21	WAP	/ P21203:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 10/07/20.
H	09	East (A)	11/14/21	DP	/ P21231:01-22	Remote visual baseline tank wall inspection revealed no areas of concern.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
H	09	East (A)	11/14/21	DP	/ P21232:01-21	Remote visual baseline inspection of the secondary vessel wall revealed no areas of concern.
H	09	South (A)	11/14/21	DP	/ P21233:01-22	Remote visual tank wall inspection revealed no changes since last evaluated on 9/11/20.
H	09	West (A)	11/14/21	DP	/ P21234:01-21	Remote visual tank wall inspection revealed no changes since last evaluated on 9/11/20.
H	10	East (A)	12/03/21	DP	/ P21278:01-20	Remote visual tank wall inspection revealed a newly identified leak-site 129 inches above tank bottom. Located on the middle girth weld ~13 feet clockwise from the East riser. Details of this finding are documented in SRR-LWE-2021-00166.
H	10	East (A)	12/03/21	DP	/ P21278:15	The magnetically mounted tank wall thermocouple was properly positioned.
H	10	North (A)	12/26/21	DP	/ P21293:01-21	Remote visual tank wall inspection revealed a previously unidentified leak-site at 110 inches above the tank bottom. This new leak-site is located on a vertical weld. Details of this finding are documented in SRR-LWE-2022-00001.
H	10	North (A)	12/26/21	DP	/ P21294:01-19	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 11/02/18.
H	10	West (A)	12/03/21	DP	/ P21279:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 12/05/20.
H	10	Center (I)	10/19/21	DSP	/ P21188:01-08	Inspection of the Submersible Transfer Pump (STP) waste transfer manifold assembly 3-way valve was satisfactory per SW.11.6-SVP-45, Section 4.32.
H	11	East (A)	12/01/21	DP	/ P21254:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 10/21/20.
H	11	East (A)	12/01/21	DP	/ P21255:01-20	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 09/08/16.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
H	11	North (A)	12/01/21	DP	/ P21256:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 10/21/20.
H	11	South (A)	12/01/21	DP	/ P21257:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 10/25/20.
H	11	West (A)	12/01/21	DP	/ P21258:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 10/25/20.
H	11	West (A)	12/01/21	DP	/ P21258:14, 19	The magnetically mounted tank wall thermocouple is properly positioned.
H	11	06 (I)	11/28/21	CCTV	/ V210782	Inspection of valves WTS-V-623, 624 and 625 was satisfactory per SW11.6-SVP-45, Section 7.9.
H	13	010 (A)	10/14/21	DP	/ P21184:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 11/08/20.
H	13	032 (A)	10/20/21	WAP	/ P21190:02	Remote visual tank wall inspection revealed no changes since last evaluated on 11/08/20.
H	13	071 (A)	10/20/21	WAP	/ P21190:03	Remote visual tank wall inspection revealed no changes since last evaluated on 11/16/20.
H	13	107 (A)	10/10/21	DP	/ P21151:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 11/08/20.
H	13	107 (A)	10/20/21	WAP	/ P21190:04	Remote visual tank wall inspection revealed no changes since last evaluated on 11/08/20.
H	13	151 (A)	10/10/21	DP	/ P21152:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 11/08/20.
H	13	151 (A)	10/10/21	DP	/ P21153:01-20	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 10/11/17.
H	13	175 (A)	10/08/21	WAP	/ P21189:01	Remote visual tank wall inspection revealed no changes since last evaluated on 11/16/20.
H	13	207 (A)	10/10/21	DP	/ P21154:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 11/08/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
H	13	207 (A)	10/10/21	DP	/ P21155:01-20	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 10/08/19.
H	13	228 (A)	10/10/21	DP	/ P21156:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 11/08/20.
H	13	East (A)	10/08/21	WAP	/ P21189:02	Remote visual tank wall inspection revealed no changes since last evaluated on 11/16/20.
H	13	North (A)	10/14/21	DP	/ P21181:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 11/16/20.
H	13	North (A)	10/14/21	DP	/ P21181:19	The magnetically mounted tank wall thermocouple was properly positioned.
H	13	South (A)	10/14/21	DP	/ P21182:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 11/16/20.
H	13	West (A)	10/14/21	DP	/ P21183:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 11/16/20.
H	14	013 (A)	10/29/21	DP	/ P21191:01-20	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 11/01/20.
H	14	013 (A)	10/30/21	WAP	/ P21213:01	Remote visual tank wall inspection revealed no changes since last evaluated on 11/01/20.
H	14	032 (A)	10/30/21	WAP	/ P21213:02	Remote visual tank wall inspection revealed no changes since last evaluated on 11/04/20.
H	14	065 (A)	10/31/21	DP	/ P21192:01-19	Remote visual tank wall inspection revealed no changes since last evaluated on 11/01/20.
H	14	065 (A)	10/31/21	DP	/ P21193:01-19	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 05/13/18.
H	14	108 (A)	10/30/21	WAP	/ P21213:03	Remote visual tank wall inspection revealed no changes since last evaluated on 11/01/20.
H	14	118 (A)	10/31/21	DP	/ P21194:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 11/04/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
H	14	125 (A)	10/30/21	DP	/ P21195:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 11/04/20.
H	14	151 (A)	10/30/21	DP	/ P21196:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 11/04/20.
H	14	169 (A)	10/29/21	DP	/ P21197:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 11/04/20.
H	14	207 (A)	10/30/21	WAP	/ P21213:04	Remote visual tank wall inspection revealed no changes since last evaluated on 11/01/20.
H	14	235 (A)	10/30/21	WAP	/ P21213:05	Remote visual tank wall inspection revealed no changes since last evaluated on 11/04/20.
H	14	259 (A)	10/29/21	DP	/ P21198:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 11/04/20.
H	14	East (A)	10/29/21	DP	/ P21199:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 11/01/20. The conductivity probe was properly positioned.
H	14	North (A)	10/30/21	DP	/ P21200:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 11/01/20.
H	14	North (A)	10/30/21	DP	/ P21200:17	The magnetically mounted tank wall thermocouple was properly positioned.
H	15	010 (A)	10/16/21	DP	/ P21176:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 03/14/20.
H	15	010 (A)	10/16/21	DP	/ P21177:01-20	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 07/03/16.
H	15	032 (A)	10/19/21	DP	/ P21185:01-21	Remote visual tank wall inspection revealed no changes since last evaluated on 03/13/20.
H	15	071 (A)	10/15/21	WAP	/ P21174:02	Remote visual inspection revealed no changes since last evaluated on 03/13/20.
H	15	107 (A)	10/15/21	WAP	/ P21174:03	Remote visual inspection revealed no changes since last evaluated on 03/14/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
H	15	171 (A)	10/15/21	WAP	/ P21174:04	Remote visual inspection revealed no changes since last evaluated on 03/14/20.
H	15	182 (A)	10/15/21	WAP	/ P21174:05	Remote visual inspection revealed no changes since last evaluated on 03/13/20.
H	15	207 (A)	10/16/21	DP	/ P21178:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 03/14/20.
H	15	207 (A)	10/16/21	DP	/ P21179:01-20	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 10/13/12.
H	15	242 (A)	10/16/21	DP	/ P21180:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 3/13/20.
H	15	242 (A)	10/16/21	DP	/ P21180:18	The magnetically mounted tank wall thermocouple was properly positioned.
H	15	East (A)	10/15/21	WAP	/ P21174:01	Remote visual inspection revealed no changes since last evaluated on 03/13/20.
H	15	North (A)	10/19/21	DP	/ P21186:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 03/13/20.
H	15	South (A)	10/16/21	DP	/ P21175:01-20	Remote visual tank wall inspection revealed no changes since last evaluated on 03/13/20.
H	15	West (A)	10/19/21	DP	/ P21187:01-22	Remote visual tank wall inspection revealed no changes since last evaluated on 03/13/20.
H	21	VB	08/28/21	CCTV	/ V210504	Inspection of the stainless steel liner, conductivity probe, cover and valves was satisfactory per SW11.6-SVP-45, Section 7.9.
H	21	NE (I)	05/13/21	CCTV	/ V210308	Remote visual inspection of the concrete dome and tank wall revealed no areas of concern since last evaluated on 05/18/20. The HLLCP was properly positioned.
H	22	NW (I)	12/18/21	CCTV	/ V210768	Remote visual inspection of the concrete dome and tank wall revealed no areas of concern since last evaluated on 10/14/20. The HLLCP was properly positioned.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
H	23	SW (I)	11/25/21	CCTV	/ V210714	Remote visual inspection of the concrete dome and tank wall revealed no areas of concern since last evaluated on 10/23/20. The HLLCP was properly positioned.
H	24	SW (I)	05/15/21	CCTV	/ V210313	Remote visual inspection of the concrete dome and tank wall revealed no areas of concern since last evaluated on 09/12/20. The HLLCP was properly positioned.
F	25	A-01 (A)	02/26/21	WAP	/ P21013:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/24/20.
F	25	A-02 (A)	02/26/21	WAP	/ P21013:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/24/20.
F	25	A-03 (A)	02/26/21	WAP	/ P21013:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/24/20.
F	25	A-04 (A)	02/26/21	WAP	/ P21013:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/24/20.
F	25	P-01 (A)	08/13/21	DP	/ P21073:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/09/20.
F	25	P-02 (A)	08/13/21	DP	/ P21074:01-26	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/09/20.
F	25	P-02 (A)	08/13/21	DP	/ P21075:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 03/21/17.
F	25	P-03 (A)	02/26/21	WAP	/ P21013:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/09/20.
F	25	P-04 (A)	02/26/21	WAP	/ P21013:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/09/20.
F	25	P-05 (A)	02/26/21	WAP	/ P21013:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/01/19.
F	25	P-06 (A)	02/26/21	WAP	/ P21013:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/09/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
F	25	P-07 (A)	08/13/21	DP	/ P21076:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/09/20.
F	25	P-08 (A)	08/13/21	DP	/ P21077:01-26	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/09/20.
F	25	P-09 (A)	08/13/21	DP	/ P21078:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/01/19.
F	25	P-09 (A)	08/13/21	DP	/ P21079:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 03/24/17.
F	25	P-10 (A)	02/26/21	WAP	/ P21013:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/09/20.
F	25	P-11 (A)	02/26/21	WAP	/ P21013:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/09/20.
F	25	P-12 (A)	02/26/21	WAP	/ P21013:11	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/09/20.
F	25	P-13 (A)	02/26/21	WAP	/ P21013:12	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/09/20.
F	25	P-14 (A)	02/26/21	WAP	/ P21013:13	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/09/20.
F	26	A-01 (A)	02/27/21	WAP	/ P21014:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/01/20.
F	26	A-02 (A)	02/27/21	WAP	/ P21014:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/01/20.
F	26	A-03 (A)	02/27/21	WAP	/ P21014:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/01/20.
F	26	A-04 (A)	02/27/21	WAP	/ P21014:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/01/20.
F	26	P-01 (A)	02/27/21	WAP	/ P21014:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/11/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
F	26	P-02 (A)	02/27/21	WAP	/ P21014:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/11/20.
F	26	P-03 (A)	11/28/21	DP	/ P21246:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/01/20.
F	26	P-04 (A)	11/28/21	DP	/ P21247:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/01/20.
F	26	P-05 (A)	02/27/21	WAP	/ P21014:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/01/20.
F	26	P-06 (A)	02/27/21	WAP	/ P21014:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/01/20.
F	26	P-07 (A)	02/27/21	WAP	/ P21014:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/11/20.
F	26	P-08 (A)	02/27/21	WAP	/ P21014:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/11/20.
F	26	P-09 (A)	02/27/21	WAP	/ P21014:11	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/11/20.
F	26	P-09 (A)	11/28/21	DP	/ P21249:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 06/29/16.
F	26	P-10 (A)	11/28/21	DP	/ P21250:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/01/20.
F	26	P-11 (A)	11/28/21	DP	/ P21251:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/01/20.
F	26	P-12 (A)	11/28/21	DP	/ P21252:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/01/20.
F	26	P-12 (A)	11/28/21	DP	/ P21253:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 03/25/17.
F	26	P-13 (A)	02/27/21	WAP	/ P21014:12	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/01/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>			<u>REMARKS</u>
F	26	P-14 (A)	02/27/21	WAP	/	P21014:13	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/01/20.
F	27	A-01 (A)	03/03/21	WAP	/	P21017:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/27/20.
F	27	A-02 (A)	03/03/21	WAP	/	P21017:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/27/20.
F	27	A-03 (A)	03/03/21	WAP	/	P21017:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/27/20.
F	27	A-04 (A)	03/03/21	WAP	/	P21017:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/27/20.
F	27	P-01 (A)	03/03/21	WAP	/	P21017:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/27/20.
F	27	P-02 (A)	08/15/21	DP	/	P21104:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/29/20.
F	27	P-03 (A)	03/03/21	WAP	/	P21017:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/29/20.
F	27	P-04 (A)	03/03/21	WAP	/	P21017:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/29/20.
F	27	P-05 (A)	03/03/21	WAP	/	P21017:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/29/20.
F	27	P-06 (A)	03/03/21	WAP	/	P21017:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/29/20.
F	27	P-07 (A)	03/03/21	WAP	/	P21017:14	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/29/20.
F	27	P-08 (A)	08/15/21	DP	/	P21105:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/29/20.
F	27	P-09 (A)	08/15/21	DP	/	P21107:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 04/08/17.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
F	27	P-09 (A)	08/15/21	DP	/ P21106:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/29/20.
F	27	P-10 (A)	03/03/21	WAP	/ P21017:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/29/20.
F	27	P-11 (A)	03/03/21	WAP	/ P21017:11	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/29/20.
F	27	P-12 (A)	08/15/21	DP	/ P21108:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 2/29/20.
F	27	P-12 (A)	12/19/21	DP	/ P21292:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 04/08/17.
F	27	P-13 (A)	03/03/21	WAP	/ P21017:12	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/29/20.
F	27	P-14 (A)	03/03/21	WAP	/ P21017:13	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/29/20.
F	28	VB-01	11/20/21	CCTV	/ V210695	Inspection of the jumpers, valves, stainless steel liner, cover and conductivity probe was satisfactory per SW11.6-SVP-45, Section 7.9.
F	28	VB-03	11/20/21	CCTV	/ V210695	Inspection of the stainless steel liner, conductivity probe, covers and jumpers was satisfactory per SW11.6-SVP-45, Section 7.9.
F	28	A-01 (A)	02/27/21	WAP	/ P21015:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.
F	28	A-02 (A)	02/27/21	WAP	/ P21015:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.
F	28	A-03 (A)	02/27/21	WAP	/ P21015:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.
F	28	A-04 (A)	02/27/21	WAP	/ P21015:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.
F	28	P-01 (A)	02/27/21	WAP	/ P21015:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/30/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
F	28	P-02 (A)	02/27/21	WAP	/ P21015:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.
F	28	P-03 (A)	08/29/21	DP	/ P21086:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.
F	28	P-04 (A)	02/27/21	WAP	/ P21015:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/30/20.
F	28	P-05 (A)	08/29/21	DP	/ P21087:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.
F	28	P-06 (A)	08/29/21	DP	/ P21088:01-27	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.
F	28	P-06 (A)	08/29/21	DP	/ P21089:01-22	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 05/14/17.
F	28	P-07 (A)	02/27/21	WAP	/ P21015:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/30/20.
F	28	P-08 (A)	08/29/21	DP	/ P21090:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.
F	28	P-09 (A)	02/27/21	WAP	/ P21015:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.
F	28	P-10 (A)	02/27/21	WAP	/ P21015:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.
F	28	P-11 (A)	02/27/21	WAP	/ P21015:11	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/30/20.
F	28	P-12 (A)	02/27/21	WAP	/ P21015:12	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/30/20.
F	28	P-13 (A)	02/27/21	WAP	/ P21015:13	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.
F	28	P-14 (A)	02/27/21	WAP	/ P21015:14	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
H	29	COP 101	04/21/21	DSP	/ P21033:01-25	Inspection of the transfer lines within the clean out port was satisfactory per T-DS-G-00001.
H	29	A-01 (A)	02/26/21	WAP	/ P21011:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/21/20.
H	29	A-02 (A)	02/26/21	WAP	/ P21011:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/21/20.
H	29	A-03 (A)	02/26/21	WAP	/ P21011:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/21/20.
H	29	A-04 (A)	02/26/21	WAP	/ P21011:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/21/20.
H	29	P-01 (A)	02/26/21	WAP	/ P21011:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/12/20.
H	29	P-02 (A)	09/14/21	DP	/ P21114:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/21/20.
H	29	P-03 (A)	02/26/21	WAP	/ P21011:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/21/20.
H	29	P-04 (A)	02/26/21	WAP	/ P21011:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/12/20.
H	29	P-05 (A)	02/26/21	WAP	/ P21011:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/12/20.
H	29	P-06 (A)	02/26/21	WAP	/ P21011:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/21/20.
H	29	P-07 (A)	02/26/21	WAP	/ P21011:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/12/20.
H	29	P-07 (A)	04/18/21	CCTV	/ V210237	Inspection verified the condition of the exterior of the sump transfer line from HDB-04 was satisfactory per T-DS-G-00001.
H	29	P-08 (A)	09/14/21	DP	/ P21116:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 08/19/17.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
H	29	P-08 (A)	09/14/21	DP	/ P21115:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/21/20.
H	29	P-09 (A)	02/26/21	WAP	/ P21011:13	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/21/20.
H	29	P-10 (A)	02/26/21	WAP	/ P21011:11	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/21/20.
H	29	P-11 (A)	09/14/21	DP	/ P21119:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 05/13/17.
H	29	P-11 (A)	09/14/21	DP	/ P21118:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/21/20.
H	29	P-12 (A)	09/14/21	DP	/ P21120:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/21/20.
H	29	P-13 (A)	02/26/21	WAP	/ P21011:12	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/21/20.
H	29	P-14 (A)	09/14/21	DP	/ P21121:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/21/20.
H	29/30	COP 104	04/21/21	DSP	/ P21035:01-23	Inspection of the transfer lines within the cleanout port was satisfactory per T-DS-G-00001.
H	29/30	COP 105	04/21/21	DSP	/ P21036:01-29	Inspection of the transfer lines within the cleanout port was satisfactory per T-DS-G-00001.
H	30	A-01 (A)	05/01/21	WAP	/ P21044:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 4/17/20.
H	30	A-02 (A)	05/01/21	WAP	/ P21044:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 4/17/20.
H	30	A-03 (A)	05/01/21	WAP	/ P21044:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 4/17/20.
H	30	P-01 (A)	05/01/21	WAP	/ P21044:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 5/19/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
H	30	P-03 (A)	05/01/21	WAP	/ P21044:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 4/17/20.
H	30	P-04 (A)	05/01/21	WAP	/ P21044:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 5/19/20.
H	30	P-05 (A)	11/26/21	DP	/ P21267:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/17/20.
H	30	P-06 (A)	05/01/21	WAP	/ P21044:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 4/17/20.
H	30	P-07 (A)	05/01/21	WAP	/ P21044:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 5/19/20.
H	30	P-08 (A)	11/26/21	DP	/ P21268:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/17/20.
H	30	P-08 (A)	11/26/21	DP	/ P21269:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 08/25/17.
H	30	P-09 (A)	05/01/21	WAP	/ P21044:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 4/17/20.
H	30	P-10 (A)	05/01/21	WAP	/ P21044:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 4/17/20.
H	30	P-11 (A)	11/26/21	DP	/ P21270:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/17/20.
H	30	P-12 (A)	05/01/21	WAP	/ P21044:11	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 5/19/20.
H	30	P-13 (A)	05/01/21	WAP	/ P21044:12	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 5/19/20.
H	31	COP 102	04/21/21	DSP	/ P21034:01-16	Inspection of the transfer lines within the cleanout port was satisfactory per T-DS-G-00001.
H	31	A-01 (A)	03/20/21	WAP	/ P21028:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/10/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>			<u>REMARKS</u>
H	31	A-02 (A)	03/20/21	WAP	/	P21028:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/10/20.
H	31	A-03 (A)	03/20/21	WAP	/	P21028:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/10/20.
H	31	A-04 (A)	03/20/21	WAP	/	P21028:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/10/20.
H	31	P-01 (A)	03/20/21	WAP	/	P21028:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/16/20.
H	31	P-02 (A)	10/13/21	DP	/	P21235:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/10/20.
H	31	P-03 (A)	03/20/21	WAP	/	P21028:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/10/20.
H	31	P-04 (A)	03/20/21	WAP	/	P21028:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/16/20.
H	31	P-05 (A)	03/20/21	WAP	/	P21028:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/16/20.
H	31	P-06 (A)	03/20/21	WAP	/	P21028:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/10/20.
H	31	P-07 (A)	03/20/21	WAP	/	P21028:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/16/20.
H	31	P-08 (A)	10/13/21	DP	/	P21236:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/10/20.
H	31	P-08 (A)	10/13/21	DP	/	P21237:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 07/22/17.
H	31	P-09 (A)	03/20/21	WAP	/	P21028:11	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/10/20.
H	31	P-10 (A)	03/20/21	WAP	/	P21028:12	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/10/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
H	31	P-11 (A)	03/20/21	WAP	/ P21028:13	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/16/20.
H	31	P-12 (A)	10/13/21	DP	/ P21238:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/10/20.
H	31	P-13 (A)	03/20/21	WAP	/ P21028:14	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/10/20.
H	31	P-14 (A)	10/13/21	DP	/ P21239:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/10/20.
H	32	COP 109	04/21/21	DSP	/ P21040:01-23	Inspection of the transfer lines within the cleanout port was satisfactory per T-DS-G-00001.
H	32	COP 110	04/21/21	DSP	/ P21041:01-33	Inspection of the transfer lines within the cleanout port was satisfactory per T-DS-G-00001.
H	32	COP 111	04/21/21	DSP	/ P21042:01-38	Inspection of the transfer lines within the cleanout port was satisfactory per T-DS-G-00001.
H	32	COP 112	04/21/21	DSP	/ P21043:01-42	Inspection of the transfer lines within the cleanout port was satisfactory per T-DS-G-00001.
H	32	A-01 (A)	04/11/21	WAP	/ P21030:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/14/20.
H	32	A-02 (A)	04/11/21	WAP	/ P21030:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/14/20.
H	32	A-03 (A)	04/11/21	WAP	/ P21030:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/14/20.
H	32	A-04 (A)	04/11/21	WAP	/ P21030:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/14/20.
H	32	P-01 (A)	04/11/21	WAP	/ P21030:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/13/20.
H	32	P-02 (A)	04/11/21	WAP	/ P21030:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/13/20.
H	32	P-03 (A)	04/11/21	WAP	/ P21030:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/14/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
H	32	P-04 (A)	04/11/21	WAP	/ P21030:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/13/20.
H	32	P-04 (A)	11/30/21	DP	/ P21259:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 06/22/16.
H	32	P-05 (A)	11/30/21	DP	/ P21260:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/14/20.
H	32	P-06 (A)	04/11/21	WAP	/ P21030:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/14/20.
H	32	P-07 (A)	04/11/21	WAP	/ P21030:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/13/20.
H	32	P-07 (A)	11/30/21	DP	/ P21261:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 06/22/16.
H	32	P-08 (A)	11/30/21	DP	/ P21262:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/14/20.
H	32	P-09 (A)	04/11/21	WAP	/ P21030:11	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/14/20.
H	32	P-10 (A)	04/11/21	WAP	/ P21030:12	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/14/20.
H	32	P-11 (A)	04/11/21	WAP	/ P21030:13	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/13/20.
H	32	P-12 (A)	11/30/21	DP	/ P21263:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/14/20.
H	32	P-12 (A)	11/30/21	DP	/ P21264:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 07/30/17.
H	32	P-13 (A)	04/11/21	WAP	/ P21030:14	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/14/20.
H	32	P-14 (A)	11/30/21	DP	/ P21265:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/14/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
H	32	P-15 (A)	11/30/21	DP	/ P21266:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/13/18.
F	33	A-01 (A)	02/23/21	WAP	/ P21010:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	33	A-02 (A)	02/23/21	WAP	/ P21010:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	33	A-03 (A)	02/23/21	WAP	/ P21010:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	33	A-04 (A)	02/23/21	WAP	/ P21010:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	33	P-01 (A)	02/23/21	WAP	/ P21010:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/02/20.
F	33	P-02 (A)	10/13/21	DP	/ P21158:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	33	P-03 (A)	02/23/21	WAP	/ P21010:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	33	P-04 (A)	02/23/21	WAP	/ P21010:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/02/20.
F	33	P-05 (A)	10/12/21	DP	/ P21157:01-24	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	33	P-06 (A)	02/23/21	WAP	/ P21010:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	33	P-07 (A)	02/23/21	WAP	/ P21010:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/02/20.
F	33	P-08 (A)	10/13/21	DP	/ P21159:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	33	P-08 (A)	10/13/21	DP	/ P21160:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 07/20/17.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD</u>		<u>IDENTIFICATION NUMBER</u>	<u>REMARKS</u>
F	33	P-09 (A)	02/23/21	WAP	/	P21010:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	33	P-10 (A)	02/23/21	WAP	/	P21010:11	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	33	P-11 (A)	02/23/21	WAP	/	P21010:12	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/02/20.
F	33	P-12 (A)	10/13/21	DP	/	P21161:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	33	P-12 (A)	10/13/21	DP	/	P21162:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 07/20/17.
F	33	P-13 (A)	02/23/21	WAP	/	P21010:13	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	33	P-14 (A)	10/13/21	DP	/	P21163:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	33	P-15 (A)	10/13/21	DP	/	P21164:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	33	P-16 (A)	02/23/21	WAP	/	P21010:14	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/02/20.
F	34	A-01 (A)	02/24/21	WAP	/	P21012:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	34	A-02 (A)	02/24/21	WAP	/	P21012:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	34	A-03 (A)	02/24/21	WAP	/	P21012:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	34	A-04 (A)	02/24/21	WAP	/	P21012:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	34	P-01 (A)	02/24/21	WAP	/	P21012:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/07/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
F	34	P-02 (A)	10/14/21	DP	/ P21165:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	34	P-03 (A)	02/24/21	WAP	/ P21012:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	34	P-04 (A)	02/24/21	WAP	/ P21012:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/07/20.
F	34	P-05 (A)	10/14/21	DP	/ P21166:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	34	P-06 (A)	02/24/21	WAP	/ P21012:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 09/10/20.
F	34	P-07 (A)	02/24/21	WAP	/ P21012:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/07/20.
F	34	P-08 (A)	10/14/21	DP	/ P21167:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	34	P-08 (A)	10/14/21	DP	/ P21168:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 07/30/17.
F	34	P-09 (A)	02/24/21	WAP	/ P21012:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	34	P-10 (A)	02/24/21	WAP	/ P21012:11	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	34	P-11 (A)	02/24/21	WAP	/ P21012:12	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/07/20.
F	34	P-12 (A)	10/14/21	DP	/ P21169:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	34	P-12 (A)	10/14/21	DP	/ P21170:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 07/30/17.
F	34	P-13 (A)	02/24/21	WAP	/ P21012:13	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
F	34	P-14 (A)	10/14/21	DP	/ P21171:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	34	P-15 (A)	10/14/21	DP	/ P21172:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/26/20.
F	34	P-16 (A)	02/24/21	WAP	/ P21012:14	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/07/20.
H	35	A-01 (A)	04/18/21	CCTV	/ V210238	Inspection verified the condition of the exterior of the sump transfer line from HDB-06 was satisfactory per T-DS-G-00001.
H	35	A-01 (A)	04/25/21	WAP	/ P21032:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/26/20.
H	35	A-02 (A)	04/25/21	WAP	/ P21032:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/26/20.
H	35	A-03 (A)	04/25/21	WAP	/ P21032:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/26/20.
H	35	A-04 (A)	04/25/21	WAP	/ P21032:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/26/20.
H	35	P-01 (A)	04/25/21	WAP	/ P21032:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/26/20.
H	35	P-02 (A)	04/25/21	WAP	/ P21032:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/26/20.
H	35	P-03 (A)	04/25/21	WAP	/ P21032:12	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/26/20.
H	35	P-04 (A)	04/25/21	WAP	/ P21032:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/26/20.
H	35	P-05 (A)	09/10/21	DP	/ P21144:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/26/20.
H	35	P-06 (A)	04/25/21	WAP	/ P21032:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/30/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
H	35	P-07 (A)	09/10/21	DP	/ P21145:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/26/20.
H	35	P-07 (A)	09/10/21	DP	/ P21146:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 07/23/17.
H	35	P-09 (A)	09/10/21	DP	/ P21147:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/26/20.
H	35	P-10 (A)	04/25/21	WAP	/ P21032:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/30/20.
H	35	P-11 (A)	09/10/21	DP	/ P21148:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/26/20.
H	35	P-11 (A)	09/10/21	DP	/ P21149:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 07/23/17.
H	35	P-12 (A)	04/25/21	WAP	/ P21032:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/30/20.
H	35	P-13 (A)	09/10/21	DP	/ P21150:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/26/20.
H	35	P-14 (A)	04/25/21	WAP	/ P21032:11	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/30/20.
H	36	A-01 (A)	01/29/21	WAP	/ P21001:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.
H	36	A-02 (A)	01/29/21	WAP	/ P21001:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.
H	36	A-03 (A)	01/29/21	WAP	/ P21001:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.
H	36	A-04 (A)	01/29/21	WAP	/ P21001:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.
H	36	P-01 (A)	01/29/21	WAP	/ P21001:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD</u>		<u>IDENTIFICATION NUMBER</u>	<u>REMARKS</u>
H	36	P-02 (A)	01/29/21	WAP	/	P21001:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.
H	36	P-03 (A)	01/29/21	WAP	/	P21001:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.
H	36	P-04 (A)	01/29/21	WAP	/	P21001:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.
H	36	P-05 (A)	09/03/21	DP	/	P21109:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.
H	36	P-06 (A)	01/29/21	WAP	/	P21001:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/25/20.
H	36	P-07 (A)	09/11/21	DP	/	P21122:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.
H	36	P-07 (A)	09/11/21	DP	/	P21123:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 07/09/17.
H	36	P-08 (A)	01/29/21	WAP	/	P21001:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/25/20.
H	36	P-09 (A)	09/03/21	DP	/	P21110:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.
H	36	P-10 (A)	01/29/21	WAP	/	P21001:11	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/25/20.
H	36	P-11 (A)	09/03/21	DP	/	P21111:01-26	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.
H	36	P-11 (A)	09/03/21	DP	/	P21112:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 07/09/17.
H	36	P-12 (A)	01/29/21	WAP	/	P21001:12	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/25/20.
H	36	P-13 (A)	09/03/21	DP	/	P21113:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/12/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
H	36	P-14 (A)	01/29/21	WAP	/ P21001:13	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/25/20.
H	37	COP 106	04/21/21	DSP	/ P21037:01-30	Inspection of the transfer lines within the cleanout port was satisfactory per T-DS-G-00001.
H	37	COP 107	04/21/21	DSP	/ P21038:01-38	Inspection of the transfer lines within the cleanout port was satisfactory per T-DS-G-00001.
H	37	COP 108	04/21/21	DSP	/ P21039:01-42	Inspection of the transfer lines within the cleanout port was satisfactory per T-DS-G-00001.
H	37	A-01 (A)	04/30/21	WAP	/ P21045:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 4/10/20.
H	37	A-02 (A)	04/30/21	WAP	/ P21045:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 4/10/20.
H	37	A-03 (A)	04/30/21	WAP	/ P21045:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 4/10/20.
H	37	A-04 (A)	04/30/21	WAP	/ P21045:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 4/10/20.
H	37	P-02 (A)	04/30/21	WAP	/ P21045:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 4/10/20.
H	37	P-03 (A)	04/30/21	WAP	/ P21045:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 4/10/20.
H	37	P-04 (A)	04/30/21	WAP	/ P21045:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 4/10/20.
H	37	P-05 (A)	12/06/21	DP	/ P21271:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/10/20.
H	37	P-06 (A)	04/30/21	WAP	/ P21045:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 6/14/20.
H	37	P-07 (A)	12/06/21	DP	/ P21272:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/10/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
H	37	P-07 (A)	12/06/21	DP	/ P21273:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 08/27/17.
H	37	P-08 (A)	04/30/21	WAP	/ P21045:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 6/14/20.
H	37	P-09 (A)	12/06/21	DP	/ P21274:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/10/20.
H	37	P-10 (A)	04/30/21	WAP	/ P21045:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 6/14/20.
H	37	P-11 (A)	12/06/21	DP	/ P21275:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/10/20.
H	37	P-11 (A)	12/06/21	DP	/ P21276:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 08/27/17.
H	37	P-12 (A)	04/30/21	WAP	/ P21045:11	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 6/14/20.
H	37	P-13 (A)	12/06/21	DP	/ P21277:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/10/20.
H	38	COP 103	06/16/21	DSP	/ P21059:01-27	Inspection of the transfer lines within the cleanout port was satisfactory per T-DS-G-00001.
H	38	A-01 (A)	02/20/21	WAP	/ P21008:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/08/20.
H	38	A-01 (A)	05/09/21	CCTV	/ V210297	Inspection verified the condition of the exterior of the sump transfer line from HDB-07 was satisfactory per T-DS-G-00001.
H	38	A-02 (A)	02/20/21	WAP	/ P21008:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/08/20.
H	38	A-03 (A)	02/20/21	WAP	/ P21008:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/08/20.
H	38	A-04 (A)	02/20/21	WAP	/ P21008:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/08/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD</u>		<u>IDENTIFICATION NUMBER</u>	<u>REMARKS</u>
H	38	P-01 (A)	02/20/21	WAP	/	P21008:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/08/20.
H	38	P-02 (A)	02/20/21	WAP	/	P21008:11	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/08/20.
H	38	P-03 (A)	02/20/21	WAP	/	P21008:12	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/08/20.
H	38	P-04 (A)	02/20/21	WAP	/	P21008:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/08/20.
H	38	P-05 (A)	09/29/21	DP	/	P21136:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/21/20.
H	38	P-05 (A)	09/29/21	DP	/	P21137:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 6/24/16.
H	38	P-06 (A)	02/20/21	WAP	/	P21008:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/21/20.
H	38	P-07 (A)	02/20/21	WAP	/	P21008:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/21/20.
H	38	P-08 (A)	02/20/21	WAP	/	P21008:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/21/20.
H	38	P-09 (A)	02/20/21	WAP	/	P21008:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/21/20.
H	38	P-10 (A)	09/29/21	DP	/	P21138:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/08/20.
H	38	P-11 (A)	09/29/21	DP	/	P21139:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/08/20.
H	38	P-12 (A)	09/29/21	DP	/	P21140:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/08/20.
H	38	P-12 (A)	09/29/21	DP	/	P21141:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 08/13/17.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
H	38	P-13 (A)	09/29/21	DP	/ P21142:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/08/20.
H	38	P-14 (A)	09/29/21	DP	/ P21143:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/08/20.
H	39	A-01 (A)	02/19/21	WAP	/ P21007:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/15/20.
H	39	A-02 (A)	02/19/21	WAP	/ P21007:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/15/20.
H	39	A-03 (A)	02/19/21	WAP	/ P21007:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/15/20.
H	39	A-04 (A)	02/19/21	WAP	/ P21007:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/15/20.
H	39	P-01 (A)	02/19/21	WAP	/ P21007:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/22/20.
H	39	P-02 (A)	02/19/21	WAP	/ P21007:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/15/20.
H	39	P-03 (A)	02/19/21	WAP	/ P21007:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/22/20.
H	39	P-04 (A)	02/19/21	WAP	/ P21007:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/15/20.
H	39	P-05 (A)	02/19/21	WAP	/ P21007:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/22/20.
H	39	P-06 (A)	02/19/21	WAP	/ P21007:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/15/20.
H	39	P-07 (A)	02/19/21	WAP	/ P21007:11	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/22/20.
H	39	P-08 (A)	02/19/21	WAP	/ P21007:12	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/22/20.
H	39	P-09 (A)	02/19/21	WAP	/ P21007:13	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/15/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
H	39	P-10 (A)	02/19/21	WAP	/ P21007:14	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/15/20.
H	39	P-11 (A)	06/11/21	DP	/ P21054:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/15/20.
H	39	P-12 (A)	06/11/21	DP	/ P21055:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/15/20.
H	39	P-12 (A)	06/11/21	DP	/ P21056:01-16	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 09/29/17.
H	39	P-13 (A)	06/11/21	DP	/ P21057:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/15/20.
H	39	P-14 (A)	06/11/21	DP	/ P21058:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/15/20.
H	40	VB	09/18/21	CCTV	/ V210537	Inspection of visible jumpers, stainless steel liner, conductivity probe and cover was satisfactory per SW11.6-SVP-45, Section 7.9.
H	40	A-01 (A)	12/21/21	DP	/ P21284:01-26	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/11/20.
H	40	A-02 (A)	12/21/21	DP	/ P21285:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/11/20. The conductivity probe was properly positioned.
H	40	A-03 (A)	12/21/21	DP	/ P21286:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/11/20. The conductivity probe was properly positioned.
H	40	A-04 (A)	12/21/21	DP	/ P21287:01-26	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/11/20. The conductivity probe was properly positioned.
H	40	P-01 (A)	03/20/21	WAP	/ P21027:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 06/17/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
H	40	P-03 (A)	03/20/21	WAP	/ P21027:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 06/17/20.
H	40	P-04 (A)	03/20/21	WAP	/ P21027:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/11/20.
H	40	P-05 (A)	03/20/21	WAP	/ P21027:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/11/20.
H	40	P-06 (A)	03/20/21	WAP	/ P21027:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/11/20.
H	40	P-07 (A)	03/20/21	WAP	/ P21027:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 06/17/20.
H	40	P-08 (A)	03/20/21	WAP	/ P21027:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/11/20.
H	40	P-09 (A)	12/21/21	DP	/ P21288:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/11/20.
H	40	P-09 (A)	12/21/21	DP	/ P21289:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 8/29/17.
H	40	P-11 (A)	03/20/21	WAP	/ P21027:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/11/20.
H	40	P-12 (A)	03/20/21	WAP	/ P21027:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/11/20.
H	40	P-13 (A)	12/21/21	DP	/ P21290:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/11/20.
H	40	P-13 (A)	12/21/21	DP	/ P21291:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 8/29/17.
H	40	P-14 (A)	03/20/21	WAP	/ P21027:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/11/20.
H	41	COP 012	09/05/21	DSP	/ P21103:01-65	Inspection of the transfer lines within the cleanout port are satisfactory per T-DS-G-00001.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>			<u>REMARKS</u>
H	41	A-01 (A)	04/03/21	WAP	/	P21031:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/11/20.
H	41	A-02 (A)	04/03/21	WAP	/	P21031:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/11/20.
H	41	A-03 (A)	04/03/21	WAP	/	P21031:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/11/20.
H	41	A-04 (A)	04/03/21	WAP	/	P21031:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/11/20.
H	41	P-01 (A)	04/03/21	WAP	/	P21031:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/11/20.
H	41	P-01 (A)	11/07/21	DP	/	P21224:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 10/21/15.
H	41	P-02 (A)	04/03/21	WAP	/	P21031:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/11/20.
H	41	P-03 (A)	04/03/21	WAP	/	P21031:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/11/20.
H	41	P-04 (A)	04/03/21	WAP	/	P21031:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/11/20.
H	41	P-05 (A)	04/03/21	WAP	/	P21031:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/30/20.
H	41	P-06 (A)	04/03/21	WAP	/	P21031:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/30/20.
H	41	P-07 (A)	04/03/21	WAP	/	P21031:11	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/30/20.
H	41	P-08 (A)	04/03/21	WAP	/	P21031:12	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/30/20.
H	41	P-09 (A)	04/03/21	WAP	/	P21031:13	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/30/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
H	41	P-10 (A)	11/07/21	DP	/ P21225:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/09/19.
H	41	P-11 (A)	11/07/21	DP	/ P21226:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/09/19.
H	41	P-12 (A)	11/07/21	DP	/ P21227:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/11/20.
H	41	P-13 (A)	11/07/21	DP	/ P21228:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/11/20.
H	41	P-13 (A)	11/07/21	DP	/ P21229:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 08/21/17.
H	41	P-14 (A)	11/07/21	DP	/ P21230:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/11/20.
H	42	VB	09/12/21	CCTV	/ V210527	Inspection of the stainless steel liner, cover, jumpers, conductivity probe and valves was satisfactory per SW11.6-SVP-45, Section 7.9.
H	42	A-01 (A)	06/12/21	DP	/ P21047:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/09/20.
H	42	A-02 (A)	06/13/21	DP	/ P21053:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/09/20.
H	42	A-03 (A)	10/17/21	DP	/ P21173:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/09/20. The conductivity probe was properly positioned.
H	42	A-04 (A)	06/12/21	DP	/ P21048:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/27/20.
H	42	P-01 (A)	03/07/21	WAP	/ P21018:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/09/20.
H	42	P-02 (A)	03/07/21	WAP	/ P21018:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/09/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD</u>		<u>IDENTIFICATION NUMBER</u>	<u>REMARKS</u>
H	42	P-03 (A)	03/07/21	WAP	/	P21018:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/09/20.
H	42	P-04 (A)	03/07/21	WAP	/	P21018:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/31/20.
H	42	P-05 (A)	03/07/21	WAP	/	P21018:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/31/20.
H	42	P-06 (A)	03/07/21	WAP	/	P21018:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/27/20.
H	42	P-07 (A)	03/07/21	WAP	/	P21018:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/09/20.
H	42	P-08 (A)	03/07/21	WAP	/	P21018:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/31/20.
H	42	P-09 (A)	03/07/21	WAP	/	P21018:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/27/20.
H	42	P-10 (A)	03/07/21	WAP	/	P21018:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/27/20.
H	42	P-11 (A)	03/07/21	WAP	/	P21018:11	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/27/20.
H	42	P-12 (A)	06/12/21	DP	/	P21049:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/09/20.
H	42	P-12 (A)	06/12/21	DP	/	P21050:01-22	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 09/01/17.
H	42	P-13 (A)	06/12/21	DP	/	P21051:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/27/20.
H	42	P-14 (A)	06/12/21	DP	/	P21052:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/27/20.
H	43	A-02 (A)	03/02/21	WAP	/	P21016:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/09/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>			<u>REMARKS</u>
H	43	A-03 (A)	03/02/21	WAP	/	P21016:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/09/20.
H	43	P-01 (A)	03/02/21	WAP	/	P21016:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/09/20.
H	43	P-03 (A)	03/02/21	WAP	/	P21016:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/09/20.
H	43	P-04 (A)	03/02/21	WAP	/	P21016:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/09/20.
H	43	P-05 (A)	03/02/21	WAP	/	P21016:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/23/20.
H	43	P-06 (A)	03/02/21	WAP	/	P21016:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/23/20.
H	43	P-07 (A)	03/02/21	WAP	/	P21016:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/23/20.
H	43	P-08 (A)	03/02/21	WAP	/	P21016:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/23/20.
H	43	P-09 (A)	03/02/21	WAP	/	P21016:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/23/20.
H	43	P-10 (A)	09/21/21	DP	/	P21130:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/09/20.
H	43	P-11 (A)	09/21/21	DP	/	P21131:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/09/20.
H	43	P-11 (A)	09/21/21	DP	/	P21132:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 06/08/17.
H	43	P-12 (A)	09/21/21	DP	/	P21133:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/09/20.
H	43	P-13 (A)	09/21/21	DP	/	P21134:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/09/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
H	43	P-14 (A)	09/21/21	DP	/ P21135:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/09/20.
F	44	A-01 (A)	08/04/21	DP	/ P21091:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/16/20.
F	44	A-02 (A)	08/04/21	DP	/ P21092:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/16/20. The conductivity probe was properly positioned.
F	44	A-03 (A)	08/04/21	DP	/ P21093:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/15/20. The conductivity probe was properly positioned.
F	44	A-04 (A)	08/04/21	DP	/ P21094:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/16/20. The conductivity probe was properly positioned.
F	44	P-01 (A)	02/25/21	WAP	/ P21005:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/16/20.
F	44	P-02 (A)	02/25/21	WAP	/ P21005:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/16/20.
F	44	P-03 (A)	02/25/21	WAP	/ P21005:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/16/20.
F	44	P-04 (A)	02/25/21	WAP	/ P21005:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/15/20.
F	44	P-05 (A)	02/25/21	WAP	/ P21005:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/16/20.
F	44	P-06 (A)	02/25/21	WAP	/ P21005:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/16/20.
F	44	P-07 (A)	02/25/21	WAP	/ P21005:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/15/20.
F	44	P-08 (A)	02/25/21	WAP	/ P21005:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/15/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
F	44	P-09 (A)	08/04/21	DP	/ P21095:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/16/20.
F	44	P-09 (A)	08/04/21	DP	/ P21096:01-19	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 05/18/17.
F	44	P-10 (A)	02/25/21	WAP	/ P21005:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/20/20.
F	44	P-11 (A)	02/25/21	WAP	/ P21005:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/20/20.
F	44	P-12 (A)	02/25/21	WAP	/ P21005:11	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/25/20.
F	44	P-13 (A)	02/25/21	WAP	/ P21005:12	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/25/20.
F	44	P-14 (A)	02/25/21	WAP	/ P21005:13	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/25/20.
F	45	A-01 (A)	07/31/21	DP	/ P21067:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/16/20.
F	45	A-02 (A)	07/31/21	DP	/ P21068:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/05/20. The conductivity probe was properly positioned.
F	45	A-03 (A)	07/31/21	DP	/ P21069:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/09/20. The conductivity probe was properly positioned.
F	45	A-04 (A)	07/31/21	DP	/ P21070:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/16/20. The conductivity probe was properly positioned.
F	45	P-01 (A)	02/20/21	WAP	/ P21009:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/02/20.
F	45	P-02 (A)	02/20/21	WAP	/ P21009:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/09/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
F	45	P-03 (A)	02/20/21	WAP	/ P21009:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/09/20.
F	45	P-04 (A)	02/20/21	WAP	/ P21009:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/09/20.
F	45	P-05 (A)	02/20/21	WAP	/ P21009:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/05/20.
F	45	P-06 (A)	02/20/21	WAP	/ P21009:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/05/20.
F	45	P-07 (A)	02/20/21	WAP	/ P21009:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/05/20.
F	45	P-08 (A)	02/20/21	WAP	/ P21009:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/09/20.
F	45	P-09 (A)	07/31/21	DP	/ P21071:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/09/20.
F	45	P-09 (A)	07/31/21	DP	/ P21072:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 5/20/17.
F	45	P-10 (A)	02/20/21	WAP	/ P21009:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/10/20.
F	45	P-11 (A)	02/20/21	WAP	/ P21009:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/10/20.
F	45	P-12 (A)	02/20/21	WAP	/ P21009:11	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/10/20.
F	45	P-13 (A)	02/20/21	WAP	/ P21009:12	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/10/20.
F	45	P-14 (A)	02/20/21	WAP	/ P21009:13	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/10/20.
F	46	A-01 (A)	07/29/21	DP	/ P21097:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/20/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
F	46	A-02 (A)	07/29/21	DP	/ P21098:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/20/20. The conductivity probe was properly positioned.
F	46	A-03 (A)	07/29/21	DP	/ P21099:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/20/20. The conductivity probe was properly positioned.
F	46	A-04 (A)	07/29/21	DP	/ P21100:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/20/20. The conductivity probe was properly positioned.
F	46	P-01 (A)	01/29/21	WAP	/ P21002:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/20/20.
F	46	P-02 (A)	01/29/21	WAP	/ P21002:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/20/20.
F	46	P-03 (A)	01/29/21	WAP	/ P21002:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/20/20.
F	46	P-04 (A)	01/29/21	WAP	/ P21002:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/20/20.
F	46	P-05 (A)	01/29/21	WAP	/ P21002:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/20/20.
F	46	P-06 (A)	01/29/21	WAP	/ P21002:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/20/20.
F	46	P-07 (A)	01/29/21	WAP	/ P21002:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/20/20.
F	46	P-08 (A)	01/29/21	WAP	/ P21002:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/20/20.
F	46	P-09 (A)	07/29/21	DP	/ P21101:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 01/20/20.
F	46	P-09 (A)	07/29/21	DP	/ P21102:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 05/27/17.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>			<u>REMARKS</u>
F	46	P-10 (A)	01/29/21	WAP	/	P21002:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/13/20.
F	46	P-11 (A)	01/29/21	WAP	/	P21002:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/13/20.
F	46	P-12 (A)	01/29/21	WAP	/	P21002:11	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/13/20.
F	46	P-13 (A)	01/29/21	WAP	/	P21002:12	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/13/20.
F	46	P-14 (A)	01/29/21	WAP	/	P21002:13	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/13/20.
F	47	A-01 (A)	07/28/21	DP	/	P21061:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/01/20.
F	47	A-02 (A)	07/28/21	DP	/	P21062:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/01/20.
F	47	A-03 (A)	07/28/21	DP	/	P21063:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/01/20. The conductivity probe was properly positioned.
F	47	A-04 (A)	07/28/21	DP	/	P21064:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/01/20. The conductivity probe is properly positioned.
F	47	P-01 (A)	02/07/21	WAP	/	P21003:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/01/20.
F	47	P-02 (A)	02/07/21	WAP	/	P21003:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/01/20.
F	47	P-03 (A)	02/07/21	WAP	/	P21003:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/01/20.
F	47	P-04 (A)	02/07/21	WAP	/	P21003:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/01/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD</u>		<u>IDENTIFICATION NUMBER</u>	<u>REMARKS</u>
F	47	P-05 (A)	02/07/21	WAP	/	P21003:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/01/20.
F	47	P-06 (A)	02/07/21	WAP	/	P21003:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/01/20.
F	47	P-07 (A)	02/07/21	WAP	/	P21003:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/01/20.
F	47	P-08 (A)	07/28/21	DP	/	P21065:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/01/20.
F	47	P-08 (A)	07/28/21	DP	/	P21066:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 05/29/17.
F	47	P-09 (A)	02/07/21	WAP	/	P21003:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/01/20.
F	47	P-10 (A)	02/07/21	WAP	/	P21003:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/21/20.
F	47	P-11 (A)	02/07/21	WAP	/	P21003:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/21/20.
F	47	P-12 (A)	02/07/21	WAP	/	P21003:11	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/21/20.
F	47	P-13 (A)	02/07/21	WAP	/	P21003:12	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/21/20.
F	47	P-14 (A)	02/07/21	WAP	/	P21003:13	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/21/20.
H	48	A-01 (A)	03/14/21	WAP	/	P21019:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/03/20.
H	48	A-02 (A)	03/14/21	WAP	/	P21019:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/03/20.
H	48	A-03 (A)	03/14/21	WAP	/	P21019:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/03/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
H	48	A-03 (A)	05/09/21	CCTV	/ V210297	Inspection verified the condition of the exterior of the sump transfer line from LDB Drain Cell was satisfactory per T-DS-G-00001.
H	48	A-04 (A)	03/14/21	WAP	/ P21019:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/03/20.
H	48	P-01 (A)	03/14/21	WAP	/ P21019:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/03/20.
H	48	P-02 (A)	03/14/21	WAP	/ P21019:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/03/20.
H	48	P-03 (A)	03/14/21	WAP	/ P21019:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/03/20.
H	48	P-04 (A)	03/14/21	DP	/ P21020:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/03/20.
H	48	P-04 (A)	03/14/21	DP	/ P21021:01-22	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 01/01/14.
H	48	P-05 (A)	03/14/21	DP	/ P21022:01-26	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/03/20.
H	48	P-05 (A)	03/14/21	DP	/ P21023:01-24	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 01/15/08.
H	48	P-06 (A)	03/14/21	WAP	/ P21019:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/03/20.
H	48	P-07 (A)	03/14/21	WAP	/ P21019:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/03/20.
H	48	P-08 (A)	03/14/21	DP	/ P21024:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/03/20.
H	48	P-08 (A)	03/14/21	DP	/ P21025:01-15	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 12/16/08.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
H	48	P-09 (A)	03/14/21	DP	/ P21026:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/03/20.
H	48	P-10 (A)	03/14/21	WAP	/ P21019:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/05/20.
H	48	P-13 (A)	03/14/21	WAP	/ P21019:11	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/05/20.
H	48	P-14 (A)	03/14/21	WAP	/ P21019:12	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/05/20.
H	49	VB	09/17/21	CCTV	/ V210535	Inspection of the stainless steel liner, jumpers, valves, conductivity probe and cover was satisfactory per SW11.6-SVP-45, Section 7.9.
H	49	A-01 (A)	08/07/21	DP	/ P21124:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/27/20.
H	49	A-02 (A)	08/07/21	DP	/ P21125:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/27/20. The conductivity probe was properly positioned.
H	49	A-03 (A)	08/07/21	DP	/ P21126:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/27/20. The conductivity probe was properly positioned.
H	49	A-04 (A)	08/07/21	DP	/ P21127:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/27/20. The conductivity probe was properly positioned.
H	49	P-01 (A)	02/17/21	WAP	/ P21006:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/27/20.
H	49	P-02 (A)	02/17/21	WAP	/ P21006:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/15/20.
H	49	P-03 (A)	02/17/21	WAP	/ P21006:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/27/20.
H	49	P-04 (A)	02/17/21	WAP	/ P21006:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/27/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD</u>		<u>IDENTIFICATION NUMBER</u>	<u>REMARKS</u>
H	49	P-05 (A)	02/17/21	WAP	/	P21006:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/15/20.
H	49	P-06 (A)	02/17/21	WAP	/	P21006:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/27/20.
H	49	P-07 (A)	02/17/21	WAP	/	P21006:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/27/20.
H	49	P-08 (A)	08/07/21	DP	/	P21128:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/27/20.
H	49	P-08 (A)	08/07/21	DP	/	P21129:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 08/23/17.
H	49	P-09 (A)	02/17/21	WAP	/	P21006:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 03/27/20.
H	49	P-10 (A)	02/17/21	WAP	/	P21006:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/09/20.
H	49	P-11 (A)	02/17/21	WAP	/	P21006:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/09/20.
H	49	P-12 (A)	02/17/21	WAP	/	P21006:11	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/09/20.
H	49	P-13 (A)	02/17/21	WAP	/	P21006:12	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/09/20.
H	49	P-14 (A)	02/17/21	WAP	/	P21006:13	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/09/20.
H	50	A-01 (A)	02/09/21	WAP	/	P21004:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/28/20.
H	50	A-02 (A)	02/09/21	WAP	/	P21004:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/28/20.
H	50	A-03 (A)	02/09/21	WAP	/	P21004:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/28/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
H	50	A-04 (A)	02/09/21	WAP	/ P21004:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/28/20.
H	50	P-01 (A)	08/08/21	DP	/ P21080:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/28/20.
H	50	P-01 (A)	08/08/21	DP	/ P21081:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 10/07/19.
H	50	P-02 (A)	08/08/21	DP	/ P21082:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/28/20.
H	50	P-03 (A)	02/09/21	WAP	/ P21004:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/28/20.
H	50	P-04 (A)	02/09/21	WAP	/ P21004:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/28/20.
H	50	P-05 (A)	02/09/21	WAP	/ P21004:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/28/20.
H	50	P-06 (A)	02/09/21	WAP	/ P21004:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/28/20.
H	50	P-07 (A)	02/09/21	WAP	/ P21004:11	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/28/20.
H	50	P-08 (A)	08/08/21	DP	/ P21083:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/28/20.
H	50	P-08 (A)	08/08/21	DP	/ P21084:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 07/22/18.
H	50	P-09 (A)	08/08/21	DP	/ P21085:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 02/28/20.
H	50	P-10 (A)	02/09/21	WAP	/ P21004:13	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/18/20.
H	50	P-11 (A)	02/09/21	WAP	/ P21004:14	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/18/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD</u>		<u>IDENTIFICATION NUMBER</u>	<u>REMARKS</u>
H	50	P-12 (A)	02/09/21	WAP	/	P21004:15	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/18/20.
H	50	P-13 (A)	02/09/21	WAP	/	P21004:16	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/18/20.
H	50	P-14 (A)	02/09/21	WAP	/	P21004:17	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/18/20.
H	51	Drain VB	09/08/21	CCTV	/	V210522	Inspection of the piping was satisfactory per T-DS-G-00001.
H	51	VB	09/09/21	CCTV	/	V210524	Inspection of the stainless steel liner, cover, valves, conductivity probe and jumpers was satisfactory per SW11.6-SVP-45, Section 7.9.
H	51	A-01 (A)	11/28/21	DP	/	P21240:01-26	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/15/20.
H	51	A-02 (A)	11/28/21	DP	/	P21241:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/15/20. The conductivity probe was properly positioned.
H	51	A-03 (A)	11/28/21	DP	/	P21242:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/15/20. The conductivity probe was properly positioned.
H	51	A-04 (A)	11/28/21	DP	/	P21243:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/15/20. The conductivity probe was properly positioned.
H	51	P-01 (A)	04/15/21	WAP	/	P21029:01	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/15/20.
H	51	P-02 (A)	04/15/21	WAP	/	P21029:02	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/15/20.
H	51	P-03 (A)	04/15/21	WAP	/	P21029:03	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/15/20.
H	51	P-04 (A)	04/15/21	WAP	/	P21029:04	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/15/20.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
H	51	P-05 (A)	04/15/21	WAP	/ P21029:05	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/15/20.
H	51	P-06 (A)	04/15/21	WAP	/ P21029:06	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/15/20.
H	51	P-07 (A)	04/15/21	WAP	/ P21029:07	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/15/20.
H	51	P-08 (A)	11/28/21	DP	/ P21244:01-25	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/15/20.
H	51	P-08 (A)	11/28/21	DP	/ P21245:01-25	Remote visual inspection of the secondary vessel wall revealed no areas of concern since last evaluated on 08/28/17.
H	51	P-09 (A)	04/15/21	WAP	/ P21029:08	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 04/15/20.
H	51	P-10 (A)	04/15/21	WAP	/ P21029:09	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/31/20.
H	51	P-11 (A)	04/15/21	WAP	/ P21029:10	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/31/20.
H	51	P-12 (A)	04/15/21	WAP	/ P21029:11	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/31/20.
H	51	P-13 (A)	04/15/21	WAP	/ P21029:12	Remote visual tank wall inspection revealed no areas of concern since last evaluated on 05/31/20.
H	96	VB	08/14/21	CCTV	/ V210490	Inspection of jumpers, valves, conductivity probe, stainless steel liner, and valve box cover was satisfactory per SW11.6-SVP-45, Section 7.9.
F	DB-02	VB-05	09/11/21	CCTV	/ V210525	Remote visual inspection of the valve box cover, stainless steel liner, conductivity probe, jumpers, valves and piping was satisfactory per SW11.6-SVP-45, Section 7.9.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD</u>		<u>IDENTIFICATION NUMBER</u>	<u>REMARKS</u>
F	DB-02	W	07/06/21	CCTV	/	V210435	Remote visual inspection of the cell covers, stainless steel liner, jumpers, valves and piping was satisfactory per SW11.6-SVP-45, Section 7.9.
H	DB-02	NE	09/19/21	CCTV	/	V210538	Remote visual inspection of the valve box cover, stainless steel liner, conductivity probe, jumpers, valves and piping was satisfactory per SW11.6-SVP-45, Section 7.9.
F	DB-03	NE	04/22/21	CCTV	/	V210243	Remote inspection of the cell covers, stainless steel liner, jumpers, valves and piping was satisfactory per SW11.6-SVP-45, Section 7.9.
F	DB-03	SW	04/22/21	CCTV	/	V210243	Remote inspection of the cell covers, stainless steel liner, jumpers, valves and piping was satisfactory per SW11.6-SVP-45, Section 7.9.
H	DB-03	VB	07/10/21	CCTV	/	V210437	Remote visual inspection of the cell covers, stainless steel liner, jumpers, valves and piping was satisfactory per SW11.6-SVP-45, Section 7.9.
F	DB-04	FLWB	06/12/21	CCTV	/	V210382	Inspection was satisfactory per T-DS-G-00001.
F	DB-04	NW	04/26/21	CCTV	/	V210249	Remote visual inspection of the cell cover, stainless steel liner, jumpers, valves and piping was satisfactory per SW11.6-SVP-4.5, Section 7.9.
H	DB-04	Sump	08/07/21	CCTV	/	V210477	Remote visual inspection of the valve box cover, stainless steel liner, conductivity probe, jumpers, valves and piping was satisfactory per SW11.6-SVP-45, Section 7.9.
H	DB-05	FLWB	07/05/21	CCTV	/	V210434	Inspection was satisfactory per T-DS-G-00001.
H	DB-05	Sump	01/27/21	CCTV	/	V210093	Remote visual inspection of the cell covers, stainless steel liner, jumpers, valves and pipes were satisfactory per SW11.6-SVP-45, Section 7.9.
H	DB-06	FLWB	08/30/21	CCTV	/	V210506	Inspection was satisfactory per T-DS-G-00001.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD</u>		<u>IDENTIFICATION NUMBER</u>	<u>REMARKS</u>
H	DB-06	NE	04/23/21	CCTV	/	V210245	Remote visual inspection of the cell covers, stainless steel liner, jumpers, valve and piping was satisfactory per SW11.6-SVP-45, Section 7.9.
H	DB-06	SW	04/23/21	CCTV	/	V210245	Remote visual inspection of the cell covers, stainless steel liner, jumpers, valve and piping was satisfactory per SW11.6-SVP-45, Section 7.9.
H	DB-07	Center	05/08/21	CCTV	/	V210292	Remote visual inspection of the cell covers, stainless steel liner, jumpers, valves and piping was satisfactory per SW11.6-SVP-45, Section 7.9.
H	DB-07	FLWB	06/13/21	CCTV	/	V210383	Inspection was satisfactory per T-DS-G-00001.
H	DB-07	Sump	05/08/21	CCTV	/	V210292	Remote visual inspection of the cell covers, stainless steel liner, jumpers, valves and piping was satisfactory per SW11.6-SVP-45, Section 7.9.
H	DB-08	FLWB	09/07/21	CCTV	/	V210521	Inspection was satisfactory per T-DS-G-00001.
H	DB-08	NE	05/10/21	CCTV	/	V210299	Inspection of the cell covers, stainless steel liner, valves, jumpers and piping was satisfactory per SW11.6-SVP-45, Section 7.9.
H	DB-08	SW	05/10/21	CCTV	/	V210299	Inspection of the cell covers, stainless steel liner, valves, jumpers and piping was satisfactory per SW11.6-SVP-45, Section 7.9.
H	EVAP-16	NE	06/26/21	CCTV	/	V210413	Inspection of the cell covers, stainless steel liner, valves, jumpers and piping was satisfactory per SW11.6-SVP-45, Section 4.5.
H	EVAP-16	Pot	09/22/21	CCTV	/	V210541	Inspection documented the conditions of the interior of the evaporator pot. Details are documented in SRR-LWE-2021-00131.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD</u>		<u>IDENTIFICATION NUMBER</u>	<u>REMARKS</u>
H	EVAP-16	SW	06/26/21	CCTV	/	V210413	Inspection of the cell covers, stainless steel liner, valves, jumpers and piping was satisfactory per SW11.6-SVP-45, Section 4.5.
H	EVAP-25	Cell	08/19/21	CCTV	/	V210493	Inspection of the cell covers, stainless steel liner, valves, jumpers and piping was satisfactory per SW11.6-SVP-45, Section 4.6.
H	EVAP-25	GDL Cell	06/05/21	CCTV	/	V210374	Inspection of the cell, cell covers, and piping was satisfactory per SW11.6-SVP-45, Section 4.6.
H	EVAP-25	Pot	08/20/21	CCTV	/	V210495	Inspection documented the conditions of the interior of the evaporator pot. Details are documented in SRR-LWE-2021-00115.
H	EVAP-25	SW	06/06/21	CCTV	/	V210377	Inspection of the cell covers, stainless steel liner, valves, and jumpers was satisfactory per SW11.6-SVP-45, Section 4.6.
F	IAL Flush Pit	IT-V-42	05/15/21	CCTV	/	V210312	Inspection was satisfactory per T-DS-G-00004.
F	IAL Flush Pit	IT-V-45	05/15/21	CCTV	/	V210312	Inspection was satisfactory per T-DS-G-00004.
H	LDB Drain Cell	Port	06/25/21	CCTV	/	V210411	Remote visual inspection of the stainless steel liner, cover, sump transfer jet, valves and piping was satisfactory per SW11.6-SVP-45, Section 7.9.
F	PP-01	SW	10/09/21	CCTV	/	V210578	Inspection of the stainless steel liner, cell covers, jumpers, valves, passive vent and piping was satisfactory per SW11.6-SVP-45, Section 7.9.
F	PP-02	Sump	07/18/21	CCTV	/	V210446	Inspection of the stainless liner, cell covers, jumpers, passive vent and piping was satisfactory per SW11.6-SVP-45, Section 7.9.
H	PP-02	NE	07/21/21	CCTV	/	V210452	Inspection of the cell covers, stainless steel liner, jumper and valves was satisfactory per SW11.6-SVP-45, Section 7.9.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD IDENTIFICATION NUMBER</u>		<u>REMARKS</u>
F	PP-03	Sump	07/18/21	CCTV	/ V210447	Inspection of the cell covers, stainless liner, jumpers, valves, passive vent and piping was satisfactory per SW11.6-SVP-45, Section 7.9.
H	PP-06	NW	07/26/21	CCTV	/ V210459	Inspection of the cell cover, stainless steel liner, jumper and valves was satisfactory per SW11.6-SVP-45, Section 7.9.
H	PP-06	Sump	07/26/21	CCTV	/ V210459	Inspection of the cell cover, stainless steel liner, jumper and valves was satisfactory per SW11.6-SVP-45, Section 7.9.
H	PP-07	NW	02/15/21	CCTV	/ V210125	Remote visual inspection of the stainless steel liner, cell covers, piping, jumpers, valves, passive vent and overflow line was satisfactory per SW11.6-SVP-45, Section 7.9.
H	PP-07	SE	02/15/21	CCTV	/ V210126	Remote visual inspection of the cell covers, piping, valves, stainless steel liner and sump jet was satisfactory per SW11.6-SVP-45, section 7.9.
H	PP-08	NW	10/07/21	CCTV	/ V210575	Inspection of the cell covers, stainless steel liner, valves, jumpers and overflow line was satisfactory per SW11.6-SVP-45, Section 7.9.
H	PP-08	SE	10/07/21	CCTV	/ V210575	Inspection of the cell covers, stainless steel liner, valves, jumpers and overflow line was satisfactory per SW11.6-SVP-45, Section 7.9.
H	PP-09	NW	10/05/21	CCTV	/ V210571	Inspection of the stainless steel liner, valves, cell covers, jumpers and piping was satisfactory per SW11.6-SVP-45, Section 7.9.
H	PP-09	SE	10/05/21	CCTV	/ V210571	Inspection of the stainless steel liner, valves, cell covers, jumpers and piping was satisfactory per SW11.6-SVP-45, Section 7.9.
H	PP-10	NW	10/03/21	CCTV	/ V210565	Inspection of the stainless steel liner, valves, cell covers and piping was satisfactory per SW11.6-SVP-45, Section 7.9.

<u>AREA</u>	<u>TANK OR ANCILLARY</u>	<u>ACCESS OPENING (A OR I)</u>	<u>DATE</u>	<u>INSPECTION METHOD</u>		<u>IDENTIFICATION NUMBER</u>	<u>REMARKS</u>
H	PP-10	SE	10/03/21	CCTV	/	V210565	Inspection of the stainless steel liner, valves, cell covers and piping was satisfactory per SW11.6-SVP-45, Section 7.9.
H	WLE	ERIP-02	08/01/21	CCTV	/	V210467	Inspection of the encasement walls, floor, cell covers, supports and transfer lines was satisfactory. No unusual conditions were observed.
H	WLE	ERIP-05	08/01/21	CCTV	/	V210467	Inspection of the encasement walls, floor, cell covers, supports and transfer lines was satisfactory. No unusual conditions were observed.
H	WLE	ERIP-06	10/18/21	CCTV	/	V210592	Inspection of the encasement walls, floor, cell cover, supports and transfer lines was satisfactory. No unusual conditions were observed.
H	WLE	ERIP-07	05/16/21	CCTV	/	V210315	Inspection of the encasement walls, floor, cell covers, supports and transfer lines was satisfactory. No unusual conditions were observed. Visual segments of transfer lines HL-241035-WTS-13 and HL-241035-WTS-L-9 HDB2 were satisfactory.

Distribution

DOE-SR

M. A. Smith, 704-S
A. J. White, 704-S
T. C. Temple, 704-S

W. J. Copeland, 704-S
P. C. Suggs, 704-S

SRS

L. D. Olson, 766-H
M. N. Borders, 766-H
J. R. Cantrell, 766-H
R. E. Edwards, 766-H
J. C. Somma, 766-H
S. H. Germain, 704-56H
K. R. Liner, 704-S
J. M. Bricker, 704-56H
N. C. Iyer (5), 773-A
S. A. Thomas, 705-1C
C. L. Bergren, 730-4B
J. D. Harris, 704-56H
J. B. Elder, 707-16E
A. S. Plummer, 707-16E
P. Gibbons, 707-8E
A. N. Bridges, 707-3E

W.C. Clark, Jr., 766-H
T. D. Burns, Jr., 766-H
S. A. Zapor, 766-H
M. A. Schmitz, 766-H
J. E. Occhipinti, 704-56H
E. Patten, 704-S
K. R. Wells, 704-56H
D. P. Chew, 766-H
J. S. Kirk, 766-H
L. B. Romanowski, 705-1C
T. W. Odom, 707-8E
J. M. Griffith, 730-4B
R. S. Waltz, 707-5E
D. L. Holland, Jr., 707-8E
C. J. Smalls, 707-5E
Administrative Record File, 730-4B