

**ENVIRONMENTAL COMPLIANCE & AREA COMPLETION PROJECTS (EC&ACP) STANDARD
OPERATING PROCEDURES, VOL. I**
Manual: C3
Procedure: ER-IDS-019-071
Revision: 3
Effective Date: 12/21/2021
Type-Class: Checklist
Page: 1 of 3
D-AREA BUBBLE TOWER COVER FIELD INSPECTION CHECKLIST
WORKING COPY

This document is a Working Copy. Prior to start of work, verify this is the latest revision per the Procedure Index.

Dylan Price

 Verified By

06/11/2024

 Date

CAUTION

The Inspector is required to IMMEDIATELY notify the Post-Closure Manager and Environmental Compliance Authority if there has been a breach or compromise of the institutional controls of this waste unit. This notification is required to be in accordance with Savannah River Site post-closure inspection procedures.

NOTE

1. Manual C3, Volume 1, Procedure ER-SOP-019, Waste Unit and IOU Inspection and Maintenance, is referenced for inspection details.
2. Steps in this checklist may be completed concurrently or in any order.

 SCHEDULED
 UNSCHEDULED

A = Satisfactory X = Unsatisfactory (Explanation required)		A or X	Observation/Corrective Action Taken
1.	VERIFY roads are accessible.	A	
2.	VERIFY grass density has no bare spots more than 3 by 3 feet in area and that woody vegetation is growing on the basin covers. REMOVE OR IDENTIFY as needed. (The height of vegetation covers should not impair visual inspection of closure covers. This will be determined by Environmental Compliance and Area Completion Projects Post Closure Inspector.)	A	

D-area Bubble Tower Cover Field Inspection Checklist


Manual: C3
 Procedure: ER-IDS-019-071
 Revision: 3
 Page: 2 of 3

 SCHEDULED

 UNSCHEDULED

A = Satisfactory	A or X	Observation/Corrective Action Taken
X = Unsatisfactory (Explanation required)		
3. VERIFY soil cover has no signs of unacceptable erosion or depressions (subsidence).	A	
4. VERIFY integrity of drainage ditches and required land grading for proper drainage is maintained, area is free of excessive erosion, sediment build-up, and any debris restricting water flow.	A	
5. VERIFY no signs of burrowing or mounding animals are not present on covers.	X	Active ant mounds on soil cover. See Map Note:1 Ref. Maint. Register PC-2024-00035
6. VERIFY there are no unauthorized excavation, digging, or construction activities over the cap.	A	
7. Other. NONE	A	

Inspected By

Dylan Price (Print Name)	 (Signature)	06/11/2024 (Date)
-----------------------------	--	----------------------


Reviewed By Post-Closure Manager

Brian Hanshew (Print Name)	 (Signature)	6/26/2024 (Date)
-------------------------------	--	---------------------

D-area Bubble Tower Cover Field Inspection Checklist

Manual: C3
Procedure: ER-IDS-019-071
Revision: 3
Page: 3 of 3

D-Area Bubble Tower Cover



NOTES: 1= Active ant mounds on soil cover. Applied 1lb. of Extinguish ant bait.

No Further Entries

VP 6-11-24

POST CLOSURE MAINTENANCE REGISTER

Index Number
Unit Name

578 D-AREA BUBBLE TOWER COVER

Watershed SAVANNAH RIVER FLOOD PLANE

AHA # AHA-ER-5534
 Work Order # N/A
 Work Group POST CLOSURE MAINTENANCE
 Priority Medium
 RCRA NO

Maintenance Number	PC-2024-00035	Maintenance Status	Complete
Inspection Date	6/6/2023	Chemical Type	Pesticide
Completion Date	6/6/2023	Chemical Name	Extinguish
		Amount Used	1.0 Pounds

Description Of Maintenance Item
 Active ant mounds on waste unit

Maintenance Item Corrected
 Applied Extinguish pesticide

Notes ER-IDS-019-071

Approved by : Brian Hanshaw - ACP Post Closure Manager

Signature

Page 4 of 4

Approval date : 6/20/24