

**ENVIRONMENTAL COMPLIANCE & AREA COMPLETION PROJECTS (EC&ACP) STANDARD  
OPERATING PROCEDURES, VOL. I**
**Manual: C3**  
**Procedure: ER-IDS-019-022**  
**Revision: 3**  
**Effective Date: 06/01/2016**  
**Type-Class: Form**  
**Page: 1 of 5**
**M-AREA HAZARDOUS WASTE MANAGEMENT FACILITY (BLDG. 904-51G) FIELD INSPECTION  
CHECKLIST**
**WORKING COPY**

This document is a Working Copy. Prior to start of work, verify this is the latest revision per the Procedure Index.

*Charles P. Carter*

Verified By

05/19/2020

Date

**CAUTION**

The Inspector shall IMMEDIATELY notify the Post-Closure Manager and Environmental Compliance Authority if there has been a breach or compromise of the institutional controls of this waste unit. This notification shall be in accordance with Savannah River Site post-closure inspection procedures.

**NOTE**

1. Manual C3, ER-SOP-019, *Waste Unit Inspection and Maintenance*, shall be referred to for inspection details.
2. Monitoring wells associated with this waste unit are maintained in accordance with EC&ACP monitoring well procedures.
3. Steps in this checklist may be completed concurrently or in any order.
4. Unsatisfactory conditions found during the inspection may be listed on the detailed map of the inspected area.

**SCHEDULED**

**UNSCHEDULED**

<b>A = Satisfactory</b>		<b>A or X</b>	<b>Observation/Corrective Action Taken</b>
<b>X = Unsatisfactory (Explanation required)</b>			
<b>1.</b>	Verify roads to waste unit are accessible.	<b>A</b>	
<b>2.</b>	Verify fence, posts, and gates that surround M-Area Settling Basin are intact, in good condition, and unattended gates are locked.	<b>A</b>	

**M-Area Hazardous Waste Management Facility (Bldg. 904-51G) Field Inspection Checklist**
 **SCHEDULED**
 **UNSCHEDULED**

<b>A = Satisfactory</b> <b>X = Unsatisfactory (Explanation required)</b>	<b>A or X</b>	<b>Observation/Corrective Action Taken</b>
3. Verify M-Area Settling Basin signs (10) and postings are in acceptable condition, have correct information, and are legible from a distance of 25 feet.	A	
4. Check integrity of drainage ditches, drain pipes and general area (including the drainage ditch to Lost Lake) for presence excessive erosion, sediment buildups any debris restricting water flow.	A	
5. Check the soil cover for signs of erosion, abnormal soil cracks, depressions (subsidence) or physical impacts.	A	
6. Visually check vegetative cover of M-Area Settling Basin for grass density, with no bare spots more than 3 feet by 3 feet in area and large weeds or woody vegetation on capped area. (The height of the vegetative cover should not impair the visual inspection of the soil cover. This will be determined by the Inspector.)	A	
7. Check for excessive vegetation growing over fences, which may obstruct warning signs or visibility of inspected area.	A	
8. Check M-Settling Basin cover for signs of burrowing animals.	A	
9. Check side slopes for slumping and any observable signs of subsidence/depressions.	A	
10. Inspect ditches for standing water, excessive vegetation and debris.	A	
11. Verify annual Topographic/Subsidence Survey has been done for current calendar year.	A	<b>COMPLETED ON 05/02/2019</b> Due to the COVID-19 pandemic SRNS Survey/Layout has been deemed as non-essential. Annual surveys will be performed when SRNS Survey/Layout returns to work.
12. Verify copies of survey results are in EC&ACP Document Control Center.	X	Due to the COVID-19 pandemic SRNS Survey/Layout has been deemed as non-essential. Annual surveys will be performed when SRNS Survey/Layout returns to work. Survey results will be placed EC&ACP Document Control Center when SRNS Survey/Layout performs them.

## M-Area Hazardous Waste Management Facility (Bldg. 904-51G) Field Inspection Checklist

Manual: C3  
 Procedure: ER-IDS-019-022  
 Revision: 3  
 Page: 3 of 5

 SCHEDULED

 UNSCHEDULED

A = Satisfactory X = Unsatisfactory (Explanation required)	A or X	Observation/Corrective Action Taken
13. Check around Lost Lake for evidence of any unauthorized activity in immediate area.	A	
14. Ensure benchmark is visible and not damaged.	A	
15. Other <del>NO FURTHER ENTRIES</del>		

CPC 05/19/2020

## Inspected By

Charles P. Carter (Print Name)	<i>Charles P. Carter</i> (Signature)	05/19/2020 (Date)
-----------------------------------	---	----------------------

## Review By Post-Closure Manager


George W. Joyner (Print Name)	<i>George W. Joyner</i> (Signature)	5/27/20 (Date)
----------------------------------	--	-------------------

M-Area Hazardous Waste Management Facility (Bldg. 904-51G) Field Inspection Checklist

Manual: C3  
Procedure: ER-IDS-019-022  
Revision: 3  
Page: 4 of 5

Map of M-Area Hazardous Waste Management Facility 904-51G

Coordinates - N5-W7



• Waste Unit Signs  
 / Access Gate


NOTES:

NO ENTRIES THIS PAGE

**M-Area Hazardous Waste Management Facility (Bldg. 904-51G) Field Inspection Checklist**

**Manual:** C3  
**Procedure:** ER-IDS-019-022  
**Revision:** 3  
**Page:** 5 of 5

**Map of M-Area Hazardous Waste Management Facility (Lost Lake)**



NOTES:

**NO ENTRIES THIS PAGE**