

ENVIRONMENTAL COMPLIANCE & AREA COMPLETION PROJECTS (EC&ACP) STANDARD OPERATING PROCEDURES, VOL. I

Manual: C3
 Procedure: ER-IDS-019-037
 Revision: 4
 Effective Date: 06/02/2016
 Type-Class: Form
 Page: 1 of 3

H-AREA INACTIVE PROCESS SEWER FIELD INSPECTION CHECKLIST

WORKING COPY

This document is a Working Copy. Prior to start of work, verify this is the latest revision per the Procedure Index.

Charles P. Carter

Verified By

2-7-18

Date

CAUTION

The Inspector shall IMMEDIATELY notify the Post-Closure Manager and Environmental Compliance Authority if there has been a breach or compromise of the institutional controls of this waste unit. This notification shall be in accordance with Savannah River Site post-closure inspection procedures.

NOTE

1. Manual C3, ER-SOP-019, *Waste Unit Inspection and Maintenance*, shall be referred to for inspection details.
2. Monitoring wells associated with this waste unit are maintained in accordance with EC&ACP Monitoring Well Procedures.
3. Steps in this checklist may be completed concurrently or in any order.

SCHEDULED

UNSCHEDULED

A = Satisfactory X = Unsatisfactory (Explanation required)		A or X	Observation/Corrective Action Taken
1.	Verify the underground piping signs are in acceptable condition, have the correct information, and are legible from a distance of 25 feet.	A	
2.	Check for excessive vegetation that may obstruct warning signs or visibility of the inspection area.	A	

H-Area Inactive Process Sewer Field Inspection Checklist

Manual: C3
 Procedure: ER-IDS-019-037
 Revision: 4
 Page: 2 of 3

 SCHEDULED

 UNSCHEDULED

A = Satisfactory X = Unsatisfactory (Explanation required)	A or X	Observation/Corrective Action Taken
3. Inspect the vegetative and/or closure cover over the pipeline for erosion, abnormal soil cracks, depressions (subsidence), standing water, or mounding.	A	
4. Check for signs of burrowing animals.	X	ACTIVE ANT MOUNDS ON SOIL COVER. SEE MAP NOTE ①. REF. MAINT. Register PC-2018-00010
5. Visually check vegetative cover for grass density with no bare spots more than 3 feet by 3 feet in area. The height of the vegetation should not impair the visual inspection of the soil cover. This will be determined by the Inspector.	X	CARRY OVER ITEM: BARE SPOT IN GRASS greater THAN 3'x3'. SEE MAP NOTE ②. REF. MAINT. Register PC-2017-00112
6. Check the survey benchmarks for damage and visibility.	A	
7. Check integrity and condition of concrete and asphalt over pipeline.	A	
8. Verify that there are no excavation digging or construction activities on the soil cover.	A	
9. Other		NO FURTHER ENTRIES CPG 2-7-18

Inspected By

CHARLES P. CARTER (Print Name)	Charles P. Carter (Signature)	2-7-18 (Date)
-----------------------------------	----------------------------------	------------------

Review By Post-Closure Manager

George W. Joyner (Print Name)	[Signature] (Signature)	2/7/18 (Date)
----------------------------------	----------------------------	------------------

POST CLOSURE MAINTENANCE REGISTER

Index Number
Unit Name

554 H-AREA INACTIVE PROCESS SEWER LINE

Watershed FOURMILE BRANCH

AHA # AHA-ER-5534
 Work Order # NA
 Work Group POST CLOSURE MAINTENANCE
 Priority Medium
 RCRA NO

Maintenance Number	PC-2018-00010	Maintenance Status	Complete
Inspection Date	2/7/2018	Chemical Type	Pesticide
Completion Date	2/7/2018	Chemical Name	Extinguish
		Amount Used	2.0 Pounds

Description Of Maintenance Item

Active ant mounds on waste unit


Maintenance Item Corrected

Applied Extinguish ant bait

Notes

Approved by : George Joyner - ACP Post Closure Manager

Signature



Approval date :

2/7/18