

**ENVIRONMENTAL COMPLIANCE & AREA COMPLETION PROJECTS (EC&ACP) STANDARD
OPERATING PROCEDURES, VOL. I**
Manual: C3
Procedure: ER-IDS-019-037
Revision: 4
Effective Date: 06/02/2016
Type-Class: Form
Page: 1 of 3
H-AREA INACTIVE PROCESS SEWER FIELD INSPECTION CHECKLIST
WORKING COPY

This document is a Working Copy. Prior to start of work, verify this is the latest revision per the Procedure Index.

Charles P. Carter

 Verified By

07/22/2020

 Date

CAUTION

The Inspector shall IMMEDIATELY notify the Post-Closure Manager and Environmental Compliance Authority if there has been a breach or compromise of the institutional controls of this waste unit. This notification shall be in accordance with Savannah River Site post-closure inspection procedures.

NOTE

1. Manual C3, ER-SOP-019, *Waste Unit Inspection and Maintenance*, shall be referred to for inspection details.
2. Monitoring wells associated with this waste unit are maintained in accordance with EC&ACP Monitoring Well Procedures.
3. Steps in this checklist may be completed concurrently or in any order.

 SCHEDULED
 UNSCHEDULED

A = Satisfactory X = Unsatisfactory (Explanation required)		A or X	Observation/Corrective Action Taken
1.	Verify the underground piping signs are in acceptable condition, have the correct information, and are legible from a distance of 25 feet.	A	
2.	Check for excessive vegetation that may obstruct warning signs or visibility of the inspection area.	A	

H-Area Inactive Process Sewer Field Inspection Checklist

Manual: C3
 Procedure: ER-IDS-019-037
 Revision: 4
 Page: 2 of 3

SCHEDULED UNSCHEDULED


A = Satisfactory X = Unsatisfactory (Explanation required)	A or X	Observation/Corrective Action Taken
3. Inspect the vegetative and/or closure cover over the pipeline for erosion, abnormal soil cracks, depressions (subsidence), standing water, or mounding.	A	
4. Check for signs of burrowing animals.	A	
5. Visually check vegetative cover for grass density with no bare spots more than 3 feet by 3 feet in area. The height of the vegetation should not impair the visual inspection of the soil cover. This will be determined by the Inspector.	A	
6. Check the survey benchmarks for damage and visibility.	A	
7. Check integrity and condition of concrete and asphalt over pipeline.	A	
8. Verify that there are no excavation digging or construction activities on the soil cover.	A	
9. Other NO FURTHER ENTRIES		

CPC 07/22/2020

Inspected By		
Charles P. Carter (Print Name)	<i>Charles P. Carter</i> (Signature)	07/22/2020 (Date)

Review By Post-Closure Manager		
George W. Joyner (Print Name)	<i>George W. Joyner</i> (Signature)	7/23/2020 (Date)

H AREA INACTIVE PROCESS SEWER



NOTES:

NOTES:

NO ENTRIES THIS PAGE