

**ENVIRONMENTAL COMPLIANCE & AREA COMPLETION PROJECTS (EC&ACP) STANDARD
OPERATING PROCEDURES, VOL. I**
Manual: C3
Procedure: ER-IDS-019-037
Revision: 4
Effective Date: 06/02/2016
Type-Class: Form
Page: 1 of 3
H-AREA INACTIVE PROCESS SEWER FIELD INSPECTION CHECKLIST
WORKING COPY

This document is a Working Copy. Prior to start of work, verify this is the latest revision per the Procedure Index.

Charles P. Carter

 Verified By

07/14/2021

 Date

CAUTION

The Inspector shall IMMEDIATELY notify the Post-Closure Manager and Environmental Compliance Authority if there has been a breach or compromise of the institutional controls of this waste unit. This notification shall be in accordance with Savannah River Site post-closure inspection procedures.

NOTE

1. Manual C3, ER-SOP-019, *Waste Unit Inspection and Maintenance*, shall be referred to for inspection details.
2. Monitoring wells associated with this waste unit are maintained in accordance with EC&ACP Monitoring Well Procedures.
3. Steps in this checklist may be completed concurrently or in any order.

 SCHEDULED
 UNSCHEDULED

A = Satisfactory		A or X	Observation/Corrective Action Taken
X = Unsatisfactory (Explanation required)			
1.	Verify the underground piping signs are in acceptable condition, have the correct information, and are legible from a distance of 25 feet.	A	
2.	Check for excessive vegetation that may obstruct warning signs or visibility of the inspection area.	A	

H-Area Inactive Process Sewer Field Inspection Checklist

SCHEDULED UNSCHEDULED

A = Satisfactory X = Unsatisfactory (Explanation required)		A or X	Observation/Corrective Action Taken
3.	Inspect the vegetative and/or closure cover over the pipeline for erosion, abnormal soil cracks, depressions (subsidence), standing water, or mounding.	A	
4.	Check for signs of burrowing animals.	X	Active Ant Mounds on Soil Cover See Map Note: 1 Reference Maintenance Register: PC-2021-00058
5.	Visually check vegetative cover for grass density with no bare spots more than 3 feet by 3 feet in area. The height of the vegetation should not impair the visual inspection of the soil cover. This will be determined by the Inspector.	A	
6.	Check the survey benchmarks for damage and visibility.	A	
7.	Check integrity and condition of concrete and asphalt over pipeline.	A	
8.	Verify that there are no excavation digging or construction activities on the soil cover.	A	
9.	Other	NO FURTHER ENTRIES	

GPC 07/14/2021

Inspected By		
Charles P. Carter (Print Name)	<i>Charles P. Carter</i> (Signature)	07/14/2021 (Date)

Review By Post-Closure Manager		
George W. Joyner (Print Name)	<i>George W. Joyner</i> (Signature)	7/19/21 (Date)

POST CLOSURE MAINTENANCE REGISTER

Index Number

Unit Name

80 H-AREA INACTIVE PROCESS SEWER LINE

Watershed FOURMILE BRANCH

AHA # AHA-ER-5534

Work Order # NA

Work Group POST CLOSURE MAINTENANCE

Priority Medium

RCRA NO

Maintenance Number PC-2021-00058

Maintenance Status Complete

Inspection Date 7/14/2021

Chemical Type Pesticide

Completion Date 7/14/2021

Chemical Name Extinguish

Amount Used 1.0 Pounds

Description Of Maintenance Item

Active ant mounds on waste unit


Maintenance Item Corrected

Applied Extinguish ant bait

Notes

Approved by : George Joyner - ACP Post Closure Manager

Signature



Approval date :

7/19/21