

**ENVIRONMENTAL COMPLIANCE & AREA COMPLETION PROJECTS (EC&ACP) STANDARD OPERATING PROCEDURES, VOL. I**

Manual: C3  
 Procedure: ER-IDS-019-055  
 Revision: 3  
 Effective Date: 08/30/2016  
 Type-Class: Form  
 Page: 1 of 3

**P-AREA EARLY CONSTRUCTION AND OPERATIONAL DISPOSAL SITE (ECODS) P-2 OPERABLE UNIT FIELD INSPECTION CHECKLIST**

**WORKING COPY**

This document is a Working Copy. Prior to start of work, verify this is the latest revision per the Procedure Index.

*Charles P. Carter*  
 Verified By

*7-17-18*  
 Date

**CAUTION**

The Inspector shall IMMEDIATELY notify the Post-Closure Manager and Environmental Compliance Authority if there has been a breach or compromise of the institutional controls of this waste unit. This notification shall be in accordance with Savannah River Site post-closure inspection procedures.

**NOTE**

1. Manual C3, ER-SOP-019, *Waste Unit Inspection and Maintenance*, shall be referred to for inspection details.
2. Steps in this checklist may be completed concurrently or in any order.

**SCHEDULED**

**UNSCHEDULED**

A = Satisfactory	X = Unsatisfactory (Explanation required)	A or X	Observation/Corrective Action Taken
1.	Verify roads are accessible. ( <i>Corrective Measures Implementation Report (CMIR)/Remedial Action Completion Report (RACR)</i> , Section 7, Note 1, may be referenced).	A	
2.	Verify waste unit warning signs (6) are in acceptable condition, have correct information, and are legible from a distance of 25 feet.	A	
3.	Check survey boundary monuments for damage and visibility.	A	


P-Area Early Construction and Operational Disposal Site (ECODS) P-2 Operable Unit Field  
Inspection Checklist


Manual: C3  
 Procedure: ER-IDS-019-055  
 Revision: 3  
 Page: 2 of 3

SCHEDULED

UNSCHEDULED

A = Satisfactory	A or X	Observation/Corrective Action Taken
X = Unsatisfactory (Explanation required)		
4. Verify there are no unauthorized excavations, digging, or construction activities within the ECOD P-2 boundaries.	A	
5. Verify signs of erosion or depression (e.g., subsidence) are not present. (CMIR/RACR, Section 7, Item 5) SRNS-RP-2010-01524.	A	
6. Verify signs of burrowing or mounding animals are not present. (CMIR/RACR, Section 7, Item 4) SRNS-RP-2010-01524.	A	
7. Other		
<del>NO FURTHER ENTRIES</del>		<del>CPL 7-17-18</del>


Inspected By		
Charles P. Carter (Print Name)	 (Signature)	7-17-18 (Date)

Review By Post-Closure Manager		
George Joyner (Print Name)	 (Signature)	8/9/18 (Date)

P-Area Early Construction and Operational Disposal Site  
(ECODS) P-2 Operable Unit Field Inspection Checklist

Manual: C3  
Procedure: ER-IDS-019-055  
Revision: 3  
Page: 3 of 3

Map of P-Area ECODS P-2 Operable Unit



NOTES:

*NO ENTRIES*

*CPC 7.17.18*