

**ENVIRONMENTAL COMPLIANCE & AREA COMPLETION PROJECTS (EC&ACP) STANDARD OPERATING PROCEDURES, VOL. I**

Manual: C3  
 Procedure: ER-IDS-019-023  
 Revision: 8  
 Effective Date: 11/11/2020  
 Type-Class: Checklist  
 Page: 1 of 4

**INTERIM SANITARY LANDFILL (BLDG. 740-10G) FIELD INSPECTION CHECKLIST**

**WORKING COPY**

This document is a Working Copy. Prior to start of work, verify this is the latest revision per the Procedure Index.

*Dylan Price*  
 Verified By

11/13/2024  
 Date

**CAUTION**

The Inspector will IMMEDIATELY notify the Post-Closure Manager and Environmental Compliance Authority if there has been a breach or compromise of the institutional controls of this waste unit. This notification will be in accordance with Savannah River Site post-closure inspection procedures.

**NOTE**

1. Manual C3, Volume 1, Procedure ER-SOP-019, Waste Unit and IOU Inspection and Maintenance, will be referred to for inspection details.
2. Monitoring wells associated with this waste unit are maintained in accordance with Environmental Compliance and Area Completion Projects (EC&ACP) Monitoring Well Procedures located at EC&ACP Homepage.
3. Steps in this checklist may be completed concurrently or in any order.

SCHEDULED

UNSCHEDULED

A = Satisfactory	A or X	Observation/Corrective Action Taken
X = Unsatisfactory (Explanation required)		
1. VERIFY roads to waste unit are accessible.	A	
2. VERIFY that the waste unit signs (5) are in acceptable condition, have the correct information and are legible from a distance of 25 feet. REFER to Manual C1, Procedure ER-AP-127, ACP Waste Unit Field Inspection and Maintenance.	A	

**Interim Sanitary Landfill (Bldg. 740-10G) Field Inspection Checklist**

Manual: C3  
 Procedure: ER-IDS-019-023  
 Revision: 8  
 Page: 2 of 4

SCHEDULED                       UNSCHEDULED

	<b>A = Satisfactory</b> <b>X = Unsatisfactory (Explanation required)</b>	<b>A or X</b>	<b>Observation/Corrective Action Taken</b>
3.	<b>VERIFY</b> that the fence is locked and in good condition.	A	
4.	<b>VERIFY</b> that there is no excavating, digging, or construction activity on the soil cover.	A	
5.	<b>CHECK</b> integrity of drainage ditches and sediment trap for the presence of excessive erosion, sediment buildup, and any debris restricting water flow.	A	
6.	<b>VERIFY</b> that no woody vegetation is growing on the soil cover. Remove or identify as needed.	A	
7.	Visually <b>CHECK</b> vegetative cover for grass density with no bare spots more than 3 feet by 3 feet in area. The height of the vegetative cover should not impair the visual inspection of the soil cover. This will be determined by the Inspector.	A	
8.	<b>CHECK</b> the soil cover for signs of erosion or depressions (subsidence).	A	
9.	<b>CHECK</b> for evidence of burrowing animals.	X	Small animals digging under the perimeter fence. see map note:1 Reference Maintenance Register: PC-2024-00088

Interim Sanitary Landfill (Bldg. 740-10G) Field Inspection Checklist

Manual: C3  
 Procedure: ER-IDS-019-023  
 Revision: 8  
 Page: 3 of 4


SCHEDULED                       UNSCHEDULED

	A = Satisfactory X = Unsatisfactory (Explanation required)	A or X	Observation/Corrective Action Taken
10.	INSPECT Gas Monitoring Wells for signs of damage.	A	
11.	CHECK the survey benchmarks for damage and visibility, AND  VERIFY the annual topographic/ subsidence survey has been performed by the end of June for the current calendar year, and the results have been submitted to the EC&ACP Document Control Center.	A	Completed on 06/11/2024  SRNS-J2000-2024-00657
12.	Other  NONE	A	

Inspected By		
Dylan Price (Print Name)	<i>Dylan Price</i> (Signature)	11/13/2024 (Date)

Reviewed By Post-Closure Manager		
Brian Hanshew (Print Name)	<i>BH</i> (Signature)	11/26/2024 (Date)

Map Interim Sanitary Landfill (Bldg. 740-10G)



NOTES: Note 1 - Small animals digging under the perimeter fence.

*No Further Entries*

*TJP  
11.13.24*

# POST CLOSURE MAINTENANCE REGISTER

**Index Number**

**Unit Name**

1510 INTERIM SANITARY LANDFILL - 740-10G

**Watershed** UPPER THREE RUNS

**AHA #** AHA-ER-5534

**Work Order #** NA

**Work Group** POST CLOSURE MAINTENANCE

**Priority** Medium

**RCRA** NO

**Maintenance Number** PC-2024-00088

**Maintenance Status** Complete

**Inspection Date** 11/13/2024

**Chemical Type** NA

**Completion Date** 11/13/2024

**Chemical Name**

**Amount Used**

**Description Of Maintenance Item**

Small animals digging under the perimeter fence.

**Maintenance Item Corrected**

Post Closure Maintenance repaired hole by filling with rock.

**Notes** ER-IDS-019-023

---

Approved by : Brian Hanshew - ACP Post Closure Manager

Signature



Approval date :

11/26/2024