

**ENVIRONMENTAL COMPLIANCE & AREA COMPLETION PROJECTS
(EC&ACP) STANDARD OPERATING PROCEDURES, VOL. I**
Manual:**C3****Procedure:****ER-IDS-019-079****Revision:****0**
**F-AREA INACTIVE PROCESS SEWER LINE (FIPSL) FIELD INSPECTION
CHECKLIST**
Effective Date:**07/30/2020****Type-Class:****Checklist****Page:****1 of 2**
WORKING COPY

This document is a Working Copy. Prior to start of work, verify this is the latest revision per the Procedure Index.



Verified By

06/08/2022

Date

CAUTION

The Inspector shall IMMEDIATELY notify the Post-Closure Manager and Environmental Compliance Authority if there has been a breach or compromise of the institutional controls of this waste unit. This notification shall be in accordance with Savannah River Site post-closure inspection procedures.

NOTE

1. Monitoring wells associated with this waste unit are maintained in accordance with EC&ACP monitoring well procedures.
2. Manual C3, ER-SOP-019, Waste Unit and IOU Inspection and Maintenance, shall be referred to for inspection details.
3. Steps in this checklist may be completed concurrently or in any order.

 SCHEDULED
 UNSCHEDULED


A = Satisfactory		A or X	Observation/Corrective Action Taken
X = Unsatisfactory (Explanation required)			
1.	Verify roads are accessible.	A	
2.	Verify there are no unauthorized excavation, digging, or construction activities on or around the trebler buildings (904-47G, 904-108G).	A	


**F-AREA INACTIVE PROCESS SEWER LINE (FIPSL) FIELD INSPECTION
CHECKLIST**

Manual: C3
 Procedure: ER-IDS-019-079
 Revision: 0
 Page: 2 of 2

SCHEDULED UNSCHEDULED

A = Satisfactory	A or X	Observation/Corrective Action Taken
X = Unsatisfactory (Explanation required)		
3. Verify excessive deterioration of trebler covers has not occurred and the covers are free from debris and vegetation.	A	

Inspected By		
Charles P. Carter		06/08/2022
Print Name	Signature	Date

Reviewed By Post Closure Manager		
Brian Hanshew		6-8-2022
Print Name	Signature	Date