

ENVIRONMENTAL COMPLIANCE & AREA COMPLETION PROJECTS (EC&ACP) STANDARD OPERATING PROCEDURES, VOL. I

Manual: C3
 Procedure: ER-IDS-019-005
 Revision: 5
 Effective Date: 09/14/2021
 Type-Class: Checklist
 Page: 1 of 3

L-AREA BINGHAM PUMP OUTAGE PITS (BLDGS. 643-2G AND 643-3G) FIELD INSPECTION CHECKLIST

WORKING COPY

This document is a Working Copy. Prior to start of work, verify this is the latest revision per the Procedure Index.

Donald A. Sahr

8/17/2023

Verified By

Date

CAUTION

The Inspector will IMMEDIATELY notify the Post-Closure Manager and Environmental Compliance Authority if there has been a breach or compromise of the institutional controls of this waste unit. This notification will be in accordance with Savannah River Site post-closure inspection procedures.

NOTE

1. Manual C3, Volume 1, Procedure ER-SOP-019, Waste Unit and IOU Inspection and Maintenance, is used as a reference for inspection details.
2. Monitoring wells associated with this waste unit are maintained in accordance with Environmental Compliance and Area Completion Projects Monitoring Well Procedures.
3. Steps in this checklist may be completed concurrently or in any order.

SCHEDULED

UNSCHEDULED

A = Satisfactory X = Unsatisfactory (Explanation required)		A or X	Observation/Corrective Action Taken
1.	VERIFY roads to waste unit are accessible.	A	
2.	VERIFY that the waste unit signs (3) are in acceptable condition, have the correct information, and are legible from a distance of 25 feet.	A	

L-Area Bingham Pump Outage Pits (Bldgs. 643-2G and 643-3G) Field Inspection Checklist

Manual: C3
 Procedure: ER-IDS-019-005
 Revision: 5
 Page: 2 of 3

SCHEDULED UNSCHEDULED


A = Satisfactory X = Unsatisfactory (Explanation required)	A or X	Observation/Corrective Action Taken
3. VERIFY that there is no excavating, digging, or construction activity on the soil cover.	A	
4. VERIFY that no woody vegetation is growing on the soil cover, AND REMOVE OR IDENTIFY as needed.	A	
5. VISUALLY CHECK vegetative cover for grass density with no bare spots more than 3 feet by 3 feet in area. (The height of the vegetation should not impair the visual inspection of the soil cover. This will be determined by the Inspector.)	A	
6. CHECK the soil cover for signs of erosion or depressions (subsidence).	A	
7. CHECK for signs of burrowing animals.	A	
8. Other	NO FURTHER ENTRIES	

DAS 8/17/23

Inspected by		
Donald A. Sahn	<i>Donald A. Sahn</i>	8/17/2023
<small>(Print Name)</small>	<small>(Signature)</small>	<small>(Date)</small>

Reviewed by Post-Closure Manager		
<i>BRIAN HANSHAW</i>	<i>Bell</i>	8-23-2023
<small>(Print Name)</small>	<small>(Signature)</small>	<small>(Date)</small>

MAP L-AREA BINGHAM PUMP OUTAGE PITS (BLDG. 643-2G & 643-3G)



NOTES: No Entries This Page
