


K-Area Bingham Pump Outage Pit (Bldg. 643-1G) Field Inspection Checklist

Manual: C3
 Procedure: ER-IDS-019-004
 Revision: 8
 Page: 2 of 3


SCHEDULED UNSCHEDULED

A = Satisfactory		A or X	Observation/Corrective Action Taken
X = Unsatisfactory (Explanation required)			
4.	VERIFY no woody vegetation is growing on soil cover, AND REMOVE OR IDENTIFY as needed.	A	
5.	VISUALLY CHECK vegetative cover for grass density with no bare spots more than 3 feet by 3 feet in area. (The height of vegetative cover should not impair visual inspection of soil cover. This will be determined by Inspector.)	A	
6.	CHECK soil cover for signs of erosion or depressions (subsidence).	A	
7.	CHECK for evidence of burrowing animals.	A	
8.	VISUALLY INSPECT concrete markers (benchmarks) to ensure they are not damaged.	A	
9.	Other NONE	A	

Inspected By		
Dylan Price <i>(Print Name)</i>	 <i>(Signature)</i>	08-17-2024 <i>(Date)</i>

Reviewed by Post-Closure Manager		
Brian Hanshew <i>(Print Name)</i>	 <i>(Signature)</i>	8-27-2024 <i>(Date)</i>

Map of K-Area Bingham Pump Outage Pit (Bldg. 643-1G)



NOTES: Inspected per ER-SOP-019, Section 5.1

No Further Entries

JH 8-17-24