

**ENVIRONMENTAL COMPLIANCE & AREA COMPLETION PROJECTS (EC&ACP) STANDARD
OPERATING PROCEDURES, VOL. I**

Manual: C3
Procedure: ER-IDS-019-019
Revision: 4
Effective Date: 02/11/2020
Type-Class: Checklist
Page: 1 of 4

**F-AREA HAZARDOUS WASTE MANAGEMENT FACILITY (BLDGS. 904-41G, 904-42G AND 904-43G)
FIELD INSPECTION CHECKLIST**

WORKING COPY

This document is a Working Copy. Prior to start of work, verify this is the latest revision per the Procedure Index.

Bronson Heise
Verified By

1/7/25
Date

CAUTION

The Post-Closure Manager and Environmental Compliance Authority is notified immediately by the inspector if there has been a breach or compromise of the institutional controls of this waste unit. Notification needs to be in accordance with Savannah River Site post-closure inspection procedures.

NOTE

1. Inspection details can be found in Manual C3, Procedure ER-SOP-019, Waste Unit Inspection and Maintenance.
2. Monitoring wells associated with this waste unit are maintained in accordance with EC&ACP Monitoring Well Procedures.
3. Steps in this checklist may be completed concurrently or in any order.
4. Previous waste unit inspections can be found in the records of Manual C3, Procedure ER-SOP-008, Post Closure Inspection F-Area Hazardous Waste Management Facility (Bldgs. 904-41G, 904-42G, and 904-43G), (U) prior to January 28th, 2014.
5. Unsatisfactory conditions found during the inspection may be listed on the detailed map of the inspected area.

SCHEDULED

UNSCHEDULED

A = Satisfactory		A or X	Observation/Corrective Action Taken
X = Unsatisfactory (Explanation required)			
1.	Verify roads to waste unit are accessible.	A	

F-Area Hazardous Waste Management Facility (Bldgs. 904-41G, 904-42G and 904-43G) Field
Inspection Checklist

Manual: C3
Procedure: ER-IDS-019-019
Revision: 4
Page: 2 of 4

SCHEDULED

UNSCHEDULED


A	= Satisfactory	A or X	Observation/Corrective Action Taken
X	= Unsatisfactory (Explanation required)		
2.	Verify waste unit signs are in acceptable condition, have correct information, and are legible from a distance of 25 feet.	A	
3.	Verify fences, posts, gates, etc., are in good condition and unattended gates are locked.	A	
4.	Check the closure cover drainage system integrity and function.	A	
5.	Inspect closure cover for erosion, abnormal soil cracks, depressions or ponding indicating subsidence.	A	
6.	Check for signs of burrowing animals.	X	Applied "18" oz of extinguish ant bait. Reference Maintenance Register: DC-2025-00005
7.	Check integrity of run on and run off control measures for excessive erosion and sediment build up or debris restricting water flow.	A	
8.	Visually check vegetative cover for grass density with no bare spots more than 3 feet by 3 feet. There should be no woody vegetation or shrubs growing within the perimeter fence. The height of the vegetative cover should not impair the visual inspection of the closure. This will be determined by the Post Closure Inspector.	A	

F-Area Hazardous Waste Management Facility (Bldgs. 904-41G, 904-42G and 904-43G) Field Inspection Checklist

Manual: C3
 Procedure: ER-IDS-019-019
 Revision: 4
 Page: 3 of 4

SCHEDULED UNSCHEDULED

A = Satisfactory X = Unsatisfactory (Explanation required)		A or X	Observation/Corrective Action Taken
9.	Visually check subsidence monitors for damage.	A	
10.	Check of the survey benchmarks for damage and visibility.	A	
11.	Check the side slopes for signs of slumping and ditches for signs of excessive erosion.	A	
12.	Verify the annual elevation surveys of the subsidence monitors have been performed for the current year and that the results have been submitted to the Document Control Center.	A	
13.	Other	A	none.


Inspected By		
Bronson Heise <small>(Print Name)</small>	 <small>(Signature)</small>	1/7/25 <small>(Date)</small>

Review By Post-Closure Manager		
BRIAN HANSHEW <small>(Print Name)</small>	 <small>(Signature)</small>	1/28/2025 <small>(Date)</small>

F-Area Hazardous Waste Management Facility (Bldgs. 904-41G, 904-42G and 904-43G) Field Inspection Checklist

Manual: C3
Procedure: ER-IDS-019-019
Revision: 4
Page: 4 of 4

Map of F-AREA HAZARDOUS WASTE MANAGEMENT FACILITY (904-41G, 904-42G, and 904-43G)



NOTES: None.

POST CLOSURE MAINTENANCE REGISTER

Index Number	Unit Name
3	F-AREA HAZARDOUS WASTE MANAGEMENT FACILITY (F-AREA SEEPAGE BASIN 904-41G)
4	F-AREA HAZARDOUS WASTE MANAGEMENT FACILITY (F-AREA SEEPAGE BASIN 904-42G)
5	F-AREA HAZARDOUS WASTE MANAGEMENT FACILITY (F-AREA SEEPAGE BASIN 904-43G)

Watershed FOURMILE BRANCH

AHA # NA
 Work Order # N/A
 Work Group POST CLOSURE MAINTENANCE
 Priority Medium
 RCRA YES

Maintenance Number	PC-2025-00005	Maintenance Status	Complete
Inspection Date	1/7/2025	Chemical Type	Pesticide
Completion Date	1/7/2025	Chemical Name	Extinguish
		Amount Used	18 Ounces

Description Of Maintenance Item
 Active ant mounds on waste unit.

Maintenance Item Corrected
 Post Closure Applied Extinguish Pesticide.

Notes ER-IDS-019-019

Approved by : Brian Hanshew - ACP Post Closure Manager

Signature



Approval date :

1/28/2025