

# POST CLOSURE MAINTENANCE REGISTER

**Index Number**
**Unit Name**

15 METALLURGICAL LABORATORY HAZARDOUS WASTE MANAGEMENT FACILITY - 904-110G

**Watershed** UPPER THREE RUNS

AHA #	AHA-ER-5534		
Work Order #	NA		
Work Group	POST CLOSURE MAINTENANCE		
Priority	Medium		
RCRA	YES		
<b>Maintenance Number</b>	PC-2021-00070	<b>Maintenance Status</b>	Complete
Inspection Date	8/11/2021	<b>Chemical Type</b>	
Completion Date	6/23/2022	<b>Chemical Name</b>	
		<b>Amount Used</b>	

**Description Of Maintenance Item**

Bottom piece of frame work tubing on the entry gate is rusted through


**Maintenance Item Corrected**

Post Closure Maintenance repaired gate with a new piece of frame work tubing

**Notes** ER-IDS-019-0020

Approved by : Brian Hanshew - ACP Post Closure Manager

Signature



Approval date : 6-28-2022