

**ENVIRONMENTAL COMPLIANCE & AREA COMPLETION PROJECTS (EC&ACP) STANDARD  
OPERATING PROCEDURES, VOL. I**
**Manual: C3**  
**Procedure: ER-IDS-019-055**  
**Revision: 4**  
**Effective Date: 10/04/2021**  
**Type-Class: Checklist**  
**Page: 1 of 3**
**P-AREA EARLY CONSTRUCTION AND OPERATIONAL DISPOSAL SITE (ECODS) P-2 OPERABLE  
UNIT FIELD INSPECTION CHECKLIST**
**WORKING COPY**

This document is a Working Copy. Prior to start of work, verify this is the latest revision per the Procedure Index.

Branson Heise \_\_\_\_\_ 12/13/24 \_\_\_\_\_  
 Verified By Date

**CAUTION**

The Inspector will IMMEDIATELY notify the Post-Closure Manager and Environmental Compliance Authority if there has been a breach or compromise of the institutional controls of this waste unit. This notification will be in accordance with Savannah River Site post-closure inspection procedures.

**NOTE**

- Manual C3, Volume 1, Procedure ER-SOP-019, Waste Unit and IOU Inspection and Maintenance, is referenced for inspection details.
- Steps in this checklist may be completed concurrently or in any order.

 **SCHEDULED**
 **UNSCHEDULED**

A = Satisfactory X = Unsatisfactory (Explanation required)	A or X	Observation/Corrective Action Taken
1. <b>VERIFY</b> roads are accessible. SRNS-RP-2010-01524, Corrective Measures Implementation Report (CMIR)/Remedial Action Completion Report (RACR), Section 7, Note 1, may be referenced.	A	
2. <b>VERIFY</b> waste unit warning signs (6) are in acceptable condition, have correct information, and are legible from a distance of 25 feet.	A	
3. <b>CHECK</b> survey boundary monuments for damage and visibility.	A	

**P-Area Early Construction and Operational Disposal Site (ECODS) P-2 Operable Unit Field  
Inspection Checklist**


Manual: C3  
 Procedure: ER-IDS-019-055  
 Revision: 4  
 Page: 2 of 3

SCHEDULED


UNSCHEDULED

<b>A = Satisfactory</b> <b>X = Unsatisfactory (Explanation required)</b>	<b>A or X</b>	<b>Observation/Corrective Action Taken</b>
4. <b>VERIFY</b> there are no unauthorized excavations, digging, or construction activities within the Early Construction and Operational Disposal Site (ECODS) P-2 boundaries.	X	Down trees with exposed root ball.  Maintenance Register PC-2024-00110
5. <b>VERIFY</b> signs of erosion or depression (e.g., subsidence) are not present. (CMIR/RACR, Section 7, Item 5).	A	
6. <b>VERIFY</b> signs of burrowing or mounding animals are not present. (CMIR/RACR, Section 7, Item 4).	A	
7. Other	A	None.

Inspected By		
<i>Bronson Heise</i> (Print Name)	 (Signature)	12/13/24 (Date)

Reviewed by Post-Closure Manager		
<i>BRIAN HANSHAW</i> (Print Name)	 (Signature)	12/19/2024 (Date)

Map of P-Area ECODS P-2 Operable Unit



NOTES: 1 = Down trees with root ball exposed.

~~No further~~

~~changes~~

FBA 12/10/24