

D-area Asbestos Pit (80-20G) Field Inspection Checklist

Manual: C3
 Procedure: ER-IDS-019-069
 Revision: 3
 Page: 2 of 3

SCHEDULED UNSCHEDULED

A = Satisfactory		A or X	Observation/Corrective Action Taken
X = Unsatisfactory (Explanation required)			
5.	VERIFY signs of burrowing or mounding animals are not present on soil covers.	A	
6.	VERIFY there are no unauthorized excavation, digging, or construction activities within the waste unit boundary.	A	
7.	Other.	X	Broken barbed wire repaired Post closure maint. reg. # PC-2024-00047


Inspected By		
Dylan Price <i>(Print Name)</i>	<i>Dylan Price</i> <i>(Signature)</i>	09/03/2024 <i>(Date)</i>

Reviewed By Post-Closure Manager		
Brian Hanshew <i>(Print Name)</i>	<i>Brian Hanshew</i> <i>(Signature)</i>	10/9/2024 <i>(Date)</i>

D-area Asbestos Pit (80-20G) Field Inspection Checklist

Manual: C3
Procedure: ER-IDS-019-069
Revision: 3
Page: 3 of 3

D-Area Asbestos Pit (80-20G)



LEGEND

- BOUNDARY MARKER (CONCRETE MONUMENT)
- ACCESS CONTROL SIGN
- LAND USE CONTROL BOUNDARY LINE

NOTES: 1 - Broken barbed wire.

No Further Entries

VP 9-3-24

POST CLOSURE MAINTENANCE REGISTER

Index Number
Unit Name

211 D-AREA ASBESTOS PIT 80-20G

578

Watershed SAVANNAH RIVER FLOOD PLANE

AHA # AHA-ER-5534
Work Order # NA
Work Group POST CLOSURE MAINTENANCE
Priority Low
RCRA NO

Maintenance Number PC-2024-00047 **Maintenance Status** Complete
Inspection Date 9/3/2024 **Chemical Type** NA
Completion Date 9/3/2024 **Chemical Name**
 Amount Used

Description Of Maintenance Item

Broken barbed wire.


Maintenance Item Corrected

Post Closure Maintenance Fixed broken barbed wire.

Notes ER-IDS-019-069

Approved by : Brian Manshew - ACP Post Closure Manager

Signature



Approval date :

10/9/2024