

**ENVIRONMENTAL COMPLIANCE & AREA COMPLETION PROJECTS (EC&ACP) STANDARD
OPERATING PROCEDURES, VOL. I**
Manual: C3
Procedure: ER-IDS-019-043
Revision: 5
Effective Date: 02/07/2022
Type-Class: Checklist
Page: 1 of 3
WARNER'S POND FIELD INSPECTION CHECKLIST
WORKING COPY

This document is a Working Copy. Prior to start of work, verify this is the latest revision per the Procedure Index.

Charles P. Carter

 Verified By

03/17/2022

 Date

CAUTION

The Inspector is required to IMMEDIATELY notify the Post-Closure Manager and Environmental Compliance Authority if there has been a breach or compromise of the institutional controls of this waste unit. This notification is made in accordance with Savannah River Site post-closure inspection procedures.

NOTE

1. Monitoring wells associated with this waste unit are maintained in accordance with Environmental Compliance and Area Completion Projects monitoring well procedures.
2. Manual C3, Volume 1, Procedure C3-ER-SOP-019, Waste Unit and IOU Inspection and Maintenance, is referenced for inspection details.
3. Steps in this checklist may be completed concurrently and in any order.

 SCHEDULED
 UNSCHEDULED

A = Satisfactory		A or X	Observation/Corrective Action Taken
X = Unsatisfactory (Explanation required)			
1.	VERIFY that the roads are accessible.	A	
2.	VERIFY that the waste unit signs (5) and the subsurface process piping signs (7) are in acceptable condition have correct information and are legible from a distance of 25 feet.	A	
3.	VERIFY that there are no excavation, digging, or construction activities on the soil cover.	A	

Warner's Pond Field Inspection Checklist

Manual: C3
 Procedure: ER-IDS-019-043
 Revision: 5
 Page: 2 of 3

SCHEDULED UNSCHEDULED


A = Satisfactory X = Unsatisfactory (Explanation required)		A or X	Observation/Corrective Action Taken
4.	CHECK the integrity of drainage ditches for the presence of excessive erosion, sediment buildup, and any debris restricting water flow.	A	
5.	VERIFY that no woody vegetation is growing on the soil cover, AND REMOVE OR IDENTIFY as needed.	A	
6.	VISUALLY CHECK the vegetative cover for grass density, with no bare spots more than 3-feet by 3-feet in area. (The height of the vegetative cover should not impair the visual inspection of the soil cover. This will be determined by the inspector.)	A	
7.	CHECK the soil cover for signs of erosion or depressions (subsidence).	A	
8.	VERIFY that monuments are visible and have not been damaged.	A	
9.	CHECK for signs of burrowing animals.	X	Active ant mounds on the soil cover. See map note: 1 Ref. Maint. Register: PC-2022-00020
10.	Other. NO FURTHER ENTRIES		

CPC 03/17/2022

Inspected By		
Charles P. Carter <i>(Print Name)</i>	<i>Charles P. Carter</i> <i>(Signature)</i>	03/17/2022 <i>(Date)</i>

Reviewed By Post-Closure Manager		
George W. Joyner <i>(Print Name)</i>	<i>George W. Joyner</i> <i>(Signature)</i>	3/24/22 <i>(Date)</i>

MAP OF WARNERS POND NORTH AND SOUTH



NOTES: 1= Active ant mounds on soil cover. Applied 3.0 lbs. of Extinguish ant bait.

NO FURTHER ENTRIES

POST CLOSURE MAINTENANCE REGISTER

Index Number**Unit Name**

27 WARNERS POND, 685-23G

Watershed STEEL CREEK

AHA # AHA-ER-5534
Work Order # NA
Work Group POST CLOSURE MAINTENANCE
Priority Medium
RCRA NO

Maintenance Number	PC-2022-00020	Maintenance Status	Complete
Inspection Date	3/17/2022	Chemical Type	Pesticide
Completion Date	3/17/2022	Chemical Name	Extinguish
		Amount Used	3.0 Pounds


Description Of Maintenance Item
Active ant mounds on waste unit

Maintenance Item Corrected
Applied Extinguish pesticide

Notes New observation.

Approved by : George Joyner ACP Post Closure Manager

Signature



Approval date :

3/24/22