

**ENVIRONMENTAL COMPLIANCE & AREA COMPLETION PROJECTS (EC&ACP) STANDARD  
OPERATING PROCEDURES, VOL. I**
**Manual: C3**  
**Procedure: ER-IDS-019-071**  
**Revision: 2**  
**Effective Date: 06/01/2016**  
**Type-Class: Form**  
**Page: 1 of 3**
**D-AREA BUBBLE TOWER COVER FIELD INSPECTION CHECKLIST**
**WORKING COPY**

This document is a Working Copy. Prior to start of work, verify this is the latest revision per the Procedure Index.



Verified By

06-10-2020

Date

**CAUTION**

The Inspector shall IMMEDIATELY notify the Post-Closure Manager and Environmental Compliance Authority if there has been a breach or compromise of the institutional controls of this waste unit. This notification shall be in accordance with Savannah River Site post-closure inspection procedures.

**NOTE**

1. Manual C3, ER-SOP-019, *Waste Unit Inspection and Maintenance*, shall be referred to for inspection details.
2. Steps in this checklist may be completed concurrently or in any order.

 **SCHEDULED**
 **UNSCHEDULED**

A = Satisfactory		A or X	Observation/Corrective Action Taken
X = Unsatisfactory (Explanation required)			
1.	Verify roads are accessible.	A	
2.	Verify grass density has no bare spots more than 3 by 3 feet in area. No woody vegetation is growing on the basin covers. Remove or identify as needed. The height of vegetation covers should not impair visual inspection of closure covers. This will be determined by EC&ACP Post Closure Inspector.	A	

D-area Bubble Tower Cover Field Inspection Checklist


Manual: C3  
 Procedure: ER-IDS-019-071  
 Revision: 2  
 Page: 2 of 3


SCHEDULED

UNSCHEDULED


A = Satisfactory		A or X	Observation/Corrective Action Taken
X = Unsatisfactory (Explanation required)			
3.	Verify soil cover has no signs of unacceptable erosion or depressions (subsidence).	A	
4.	Verify integrity of drainage ditches and required land grading for proper drainage is maintained, area is free of excessive erosion, sediment build-up, and any debris restricting water flow.	A	
5.	Verify signs of burrowing or mounding animals are not present on covers.	X	Active ant mounds on soil cover. See map note:1 Ref. maint. register PC-2020-0036
6.	Verify there are no unauthorized excavation, digging or construction activities over the cap.	A	
7.	Other	<b>NO FURTHER ENTRIES</b>	

CPC 06/10/2020

Inspected By		
Charles P. Carter (Print Name)	 (Signature)	06/10/2020 (Date)

Review By Post-Closure Manager		
George W. Joyner (Print Name)	 (Signature)	6/15/2020 (Date)

D-Area Bubble Tower Cover



NOTES: 1=Active ant mounds on soil cover. Applied 0.25 lbs. of extinguish ant bait.

~~NO FURTHER ENTRIES~~

# POST CLOSURE MAINTENANCE REGISTER

**Index Number**

**Unit Name**

578 D-AREA BUBBLE TOWER COVER

**Watershed** SAVANNAH RIVER FLOOD PLANE

AHA # AHA-ER-5534

Work Order # N/A

Work Group POST CLOSURE MAINTENANCE

Priority Medium

RCRA NO

**Maintenance Number** PC-2020-00036

Maintenance Status Complete

Inspection Date 6/10/2020

Chemical Type Pesticide

Completion Date 6/10/2020

Chemical Name Extinguish

Amount Used 0.25 Pounds

**Description Of Maintenance Item**

Active ant mounds on waste unit

**Maintenance Item Corrected**


Applied Extinguish pesticide

**Notes** New observation

---

Approved by : George Joyner - ACP Post Closure Manager

Signature



Approval date :

6/15/2020