

**ENVIRONMENTAL COMPLIANCE & AREA COMPLETION PROJECTS (EC&ACP) STANDARD
OPERATING PROCEDURES, VOL. I**
Manual: C3
Procedure: ER-IDS-019-026
Revision: 5
Effective Date: 04/19/2022
Type-Class: Checklist
Page: 1 of 3
**R-BINGHAM PUMP OUTAGE PIT AND UNKNOWN PITS OPERABLE UNIT FIELD INSPECTION
CHECKLIST**
WORKING COPY

This document is a Working Copy. Prior to start of work, verify this is the latest revision per the Procedure Index.


 Verified By

06/10/2022

Date

CAUTION

The Inspector is required to IMMEDIATELY notify the Post-Closure Manager and Environmental Compliance Authority if there has been a breach or compromise of the institutional controls of this waste unit. This notification is in accordance with Savannah River Site post-closure inspection procedures.

NOTE

1. Manual C3, Volume 1, Procedure ER-SOP-019, Waste Unit and IOU Inspection and Maintenance, is referenced for inspection details.
2. Monitoring wells associated with this waste unit are maintained in accordance with Environmental Compliance and Area Completion Projects Monitoring Well Procedures.
3. Steps in this checklist may be completed concurrently or in any order.

 SCHEDULED
 UNSCHEDULED

A = Satisfactory		A or X	Observation/Corrective Action Taken
X = Unsatisfactory (Explanation required)			
1.	VERIFY roads to waste unit are accessible.	A	
2.	VERIFY that the waste unit signs (4) are in acceptable condition, have the correct information and are legible from a distance of 25 feet.	A	

R-Bingham Pump Outage Pit and Unknown Pits Operable Unit Field Inspection Checklist

Manual: C3
 Procedure: ER-IDS-019-026
 Revision: 5
 Page: 2 of 3


SCHEDULED UNSCHEDULED

A = Satisfactory X = Unsatisfactory (Explanation required)		A or X	Observation/Corrective Action Taken
3.	VERIFY there is no unauthorized digging, excavation, or construction activities on the soil cover.	A	
4.	VERIFY that no woody vegetation is growing on the existing cleared areas of the soil cover, AND REMOVE OR IDENTIFY as needed.	A	
5.	Visually CHECK vegetative cover for grass density with no bare spots more than 3 feet by 3 feet in area. (The height of the vegetation should not impair the visual inspection of the soil cover. This will be determined by the Inspector.)	A	
6.	CHECK the soil cover for signs of erosion or depressions (subsidence).	A	
7.	CHECK for signs of burrowing animals.	X	Active ant mounds on soil cover. See map note:1 Ref. Maint. Register: PC-2022-00048
8.	Other	NO FURTHER ENTRIES	JHT 06/10/2022


Inspected By

John H. Thomas (Print Name)	 (Signature)	06/10/2022 (Date)
--------------------------------	--	----------------------

Reviewed By Post-Closure Manager

Brian Hanshew (Print Name)	 (Signature)	6-28-2022 (Date)
-------------------------------	---	---------------------

MAP R-BINGHAM PUMP OUTAGE PITS (643-8G, 643-9G AND 643-10G) AND R-AREA UNKNOWN PITS 1, 2 & 3 (RUNK 1, 2, & 3)



NOTES: 1= Active ant mounds on soil cover. Applied 2.0 lbs. of Extinguish ant bait.

NO FURTHER ENTRIES

POST CLOSURE MAINTENANCE REGISTER

Index Number	Unit Name
113	R-AREA BINGHAM PUMP OUTAGE PITS - 643-10G
115	R-AREA BINGHAM PUMP OUTAGE PITS - 643-9G
114	R-AREA BINGHAM PUMP OUTAGE PITS - 643-8G

Watershed LOWER THREE RUNS

AHA # AHA-ER-5534
Work Order # N/A
Work Group POST CLOSURE MAINTENANCE
Priority Medium
RCRA NO

Maintenance Number	PC-2022-00048	Maintenance Status	Complete
Inspection Date	6/10/2022	Chemical Type	Pesticide
Completion Date	6/10/2022	Chemical Name	Extinguish
		Amount Used	2.0 Pounds

Description Of Maintenance Item
Active ant mounds on waste unit

Maintenance Item Corrected
Applied Extinguish ant bait pesticide

Notes ER-IDS-019-026

Approved by : Brian Hanshaw - ACP Post Closure Manager

Signature  Approval date : 6-28-2022