

**ENVIRONMENTAL COMPLIANCE & AREA COMPLETION PROJECTS (EC&ACP) STANDARD  
OPERATING PROCEDURES, VOL. I**
**Manual: C3**  
**Procedure: ER-IDS-019-006**  
**Revision: 6**  
**Effective Date: 09/14/2021**  
**Type-Class: Checklist**  
**Page: 1 of 3**
**P-AREA BINGHAM PUMP OUTAGE PIT (BLDG. 643-4G) FIELD INSPECTION CHECKLIST**
**WORKING COPY**

This document is a Working Copy. Prior to start of work, verify this is the latest revision per the Procedure Index.

*Charles P. Carter*  
 \_\_\_\_\_  
 Verified By

08/18/2022  
 \_\_\_\_\_  
 Date

**CAUTION**

The Inspector will IMMEDIATELY notify the Post-Closure Manager and Environmental Compliance Authority if there has been a breach or compromise of the institutional controls of this waste unit. This notification will be in accordance with Savannah River Site post-closure inspection procedures.

**NOTE**

1. Manual C3, Volume 1, Procedure ER-SOP-019, Waste Unit and IOU Inspection and Maintenance, is used as a reference for inspection details.
2. Monitoring wells associated with this waste unit are maintained in accordance with Environmental Compliance and Area Completion Projects monitoring well procedures.
3. Steps in this checklist may be completed concurrently or in any order.

 **SCHEDULED**
 **UNSCHEDULED**

A = Satisfactory		A	or	X	Observation/Corrective Action Taken
X = Unsatisfactory (Explanation required)					
1.	VERIFY roads to waste unit are accessible.	A			
2.	VERIFY waste unit signs (2) are in acceptable condition, have the correct information, and are legible from a distance of 25 feet.	A			

P-Area Bingham Pump Outage Pit (Bldg. 643-4G) Field Inspection Checklist

Manual: C3  
 Procedure: ER-IDS-019-006  
 Revision: 6  
 Page: 2 of 3

SCHEDULED                       UNSCHEDULED


A = Satisfactory		A or X	Observation/Corrective Action Taken
X = Unsatisfactory (Explanation required)			
3.	VERIFY there is no excavating, digging, or construction activity on the soil cover.	A	
4.	VERIFY no woody vegetation is growing on the soil cover, AND REMOVE OR IDENTIFY as needed.	A	
5.	VISUALLY CHECK vegetative cover for grass density with no bare spots more than 3 feet by 3 feet in area. (The height of the vegetative cover should not impair the visual inspection of the soil cover. This will be determined by the Inspector.)	A	
6.	CHECK soil cover for signs of erosion or depressions (subsidence).	A	
7.	CHECK for signs of burrowing animals.	X	Active Ant Mounds on Soil Cover See Map Note: 1 Reference Maintenance Register: PC-2022-00084
8.	Other	<del>NO FURTHER ENTRIES</del>	

CPC 08/18/2022

Inspected by		
Charles P. Carter (Print Name)	<i>Charles P. Carter</i> (Signature)	08/18/2022 (Date)

Reviewed by Post-Closure Manager		
Brian Hanshew (Print Name)	<i>B. Hanshew</i> (Signature)	8-30-22 (Date)

Map of P-Area Bingham Pump Outage Pit (Bldg. 643-4G)



**NOTES:** 1= Active ant mounds on soil cover. Applied 0.5 lb. of Extinguish ant bait.

~~NO FURTHER ENTRIES~~

# POST CLOSURE MAINTENANCE REGISTER

**Index Number**

**Unit Name**

107 P-AREA BINGHAM PUMP OUTAGE PIT - 643-4G

**Watershed** LOWER THREE RUNS

AHA # AHA-ER-5534

Work Order # N/A

Work Group POST CLOSURE MAINTENANCE

Priority Medium

RCRA NO

**Maintenance Number** PC-2022-00084

**Maintenance Status** Complete

Inspection Date 8/18/2022

**Chemical Type** Pesticide

Completion Date 8/18/2022

**Chemical Name** Extinguish

**Amount Used** 0.5 Pounds

**Description Of Maintenance Item**

Active ant mounds on waste unit

**Maintenance Item Corrected**


Applied Extinguish ant bait pesticide

**Notes** New observation.

---

Approved by : Brian Hanshew - ACP Post Closure Manager

Signature



Approval date : 8-30-22