

**ENVIRONMENTAL COMPLIANCE & AREA COMPLETION PROJECTS (EC&ACP) STANDARD
OPERATING PROCEDURES, VOL. I**

Manual: C3
Procedure: ER-IDS-019-052
Revision: 2
Effective Date: 06/01/2016
Type-Class: Form
Page: 1 of 3

**R-AREA EARLY CONSTRUCTION AND OPERATIONAL DISPOSAL SITES (ECODS) 1A, 1B, AND 1C
OPERABLE UNIT FIELD INSPECTION CHECKLIST**

WORKING COPY

This document is a Working Copy. Prior to start of work, verify this is the latest revision per the Procedure Index.

Richard Feagin

Richard Feagin
 Verified By

3/22/2021

Date

CAUTION

The Inspector shall IMMEDIATELY notify the Post-Closure Manager and Environmental Compliance Authority if there has been a breach or compromise of the institutional controls of this waste unit. This notification shall be in accordance with Savannah River Site post-closure inspection procedures.

NOTE

1. Manual C3, ER-SOP-019, *Waste Unit Inspection and Maintenance*, shall be referred to for inspection details.
2. Steps in this checklist may be completed concurrently or in any order.

SCHEDULED

UNSCHEDULED

A = Satisfactory	X = Unsatisfactory (Explanation required)	A or X	Observation/Corrective Action Taken
1.	Verify roads are accessible. (REFER TO <i>Corrective Measures Implementation Report (CMIR)/Remedial Action Completion Report (RACR)</i> , Section 7, Note 1. SRNS-RP-2010-01524.	A	
2.	Verify waste unit warning signs (9) are in acceptable condition, have correct information, and are legible from a distance of 25 feet.	A	

R-Area Early Construction and Operational Disposal Sites (ECODS) 1A, 1B, and 1C Operable Unit
Field Inspection Checklist

Manual: C3
 Procedure: ER-IDS-019-052
 Revision: 2
 Page: 2 of 3

SCHEDULED UNSCHEDULED


A = Satisfactory X = Unsatisfactory (Explanation required)		A or X	Observation/Corrective Action Taken
3.	Check survey boundary monuments for damage and visibility.	A	
4.	Verify there are no unauthorized excavations, digging, or construction activities within the ECOD 1A, 1B, and 1C boundaries.	A	
5.	Verify signs of erosion or depression (subsidence) is not present. (REFER TO CMIR/RACR, Section 7, Item 5) SRNS-RP-2010-01524.	A	
6.	Verify signs of burrowing or mounding animals are not present. (REFER TO CMIR/RACR, Section 7, Item 4) SRNS-RP-2010-01524.	X	Active ant mounds on soil cover See map note:1 Reference Maintenance Register: PC-2021-00019
7.	Other	NO FURTHER ENTRIES	

RGF 3/22/2021

Inspected By

Richard G. Feagin (Print Name)	 (Signature)	3/22/2021 (Date)
-----------------------------------	---	---------------------


Review By Post-Closure Manager

George W. Joyner (Print Name)	 (Signature)	3/23/2021 (Date)
----------------------------------	---	---------------------

R-Area Early Construction and Operational Disposal Sites
(ECODS) 1A, 1B, and 1C Operable Unit Field Inspection
Checklist

Manual: C3
Procedure: ER-IDS-019-052
Revision: 2
Page: 3 of 3

Map of R-Area ECODS 1A, 1B, 1C Operable Unit



POST CLOSURE MAINTENANCE REGISTER

Index Number

Unit Name

540 R AREA ECODS 1A, 1B, 1C OPERABLE UNIT

Watershed LOWER THREE RUNS

AHA # AHA-ER-5534
Work Order # N/A
Work Group POST CLOSURE MAINTENANCE
Priority Medium
RCRA NO

Maintenance Number	PC-2021-00019	Maintenance Status	Complete
Inspection Date	3/22/2021	Chemical Type	Pesticide
Completion Date	3/22/2021	Chemical Name	Extinguish
		Amount Used	.5 Pounds


Description Of Maintenance Item
Active ant mounds on waste unit

Maintenance Item Corrected
Applied Extinguish pesticide

Notes New observation. Applied .5 lbs. of Extinguish pesticide.

Approved by : George Joyner - ACP Post Closure Manager

Signature



Approval date :

3/23/2021