

POST CLOSURE MAINTENANCE REGISTER

Index Number
Unit Name

68 D-AREA ASH BASIN (488-D)

Watershed UPPER THREE RUNS

| | | | |
|---------------------------|--------------------------|---------------------------|----------|
| AHA # | AHA-ER-5534 | | |
| Work Order # | N/A | | |
| Work Group | POST CLOSURE MAINTENANCE | | |
| Priority | Medium | | |
| RCRA | NO | | |
| Maintenance Number | PC-2021-00119 | Maintenance Status | Complete |
| Inspection Date | 12/17/2021 | Chemical Type | NA |
| Completion Date | 3/8/2022 | Chemical Name | |
| | | Amount Used | |

Description Of Maintenance Item

Broken PVC piping plug on drainage system located in the Northwest corner


Maintenance Item Corrected

Post Closure Maintenance replaced broken PVC piping plug on drainage system located in the Northwest corner

Notes New observation

Approved by : George Joyner - ACP Post Closure Manager

Signature



Approval date :

3/9/22